

	<h2 style="color: #E67E22;">LB1950V-MPB-E</h2>
	Manufacturer Part Number: LB1950V-MPB-E
	Manufacturer/Brand: AMI Semiconductor / ON Semiconductor
	Part of Description: IC MOTOR DRIVER 3PH SL 30SSOP
	RoHs Status:  Lead free / RoHS
	Stock Condition: ^{Compliant} New original, Stock Available.
	Ship From: Hong Kong
	Shipment Way: DHL/Fedex/TNT/UPS/EMS
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	LB1950V-MPB-E
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER 3PH SL 30SSOP
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	*
Mounting Type	Surface Mount
Package / Case	30-LSSOP (0.220", 5.60mm Width)
Supplier Device Package	30-SSOP
Packaging	Tube

LB1950V-MPB-E is New Original in Stock, Search LB1950V-MPB-E Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1950V-MPB-E AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1950V-MPB-E : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>LB1948MC-BH AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR MFP10S</p>	 <p>LB1950V-TLM SANYO LB1950V-TLM SANYO</p>	 <p>LB1948MC-AH AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 10MFPSK</p>	 <p>LB1948MC-ZH AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 10MFPSK</p>
 <p>LB1950V-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER 3PH SL 30SSOP</p>	 <p>LB1951 SANYO LB1951 SANYO</p>	 <p>LB194S SANYO SANYO HSOP</p>	 <p>LB1951V-TRM SANYO LB1951V-TRM SANYO</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|---------------------|---------------------|------------------------|
| ⊕ 06031A3R6DAT2A | ↔ 08053C334JAT2A | ⇒ 1210GC221KAT1A | D 7MBP300RA060-05 | ⇒ ADDI9000BCBZRL |
| ⊖ BA78M24FP-E2 | ⊕ C0603CH1H180J030BA | D CDRH2D18/LD-100NC | ⇒ CFRM103-G | ⇒ CGJ2B2X7R1C682K050BA |
| ⊕ CL31C271JBCNNNC | ⊖ CVM100BB60 | ⊕ CY62128VLL-707AI | ↔ DD76N08L | ⇒ DM74157N |
| D EP4CE40F23C8N | ⊕ FAN77011MTCX | ⊖ FDP51N25 | ⊕ FJZ594JBTF | ⇒ FSU10A40 |
| ⇒ GRM1555C1E6R7DZ01D | ↔ GRM1555C1H1R7BZ01D | ⊕ H11A2TVM | ⊖ HFA3861BIN | ⇒ HTP100CPT/2K |
| ↔ HVDA541QDRQ1 | ⇒ IRDAKO705170 | D IRFP9140 | ⊕ LT1511ISW#PBF | ⊖ MAX2644EXT-T |
| ⊕ MSB710-RT1 | D PCA9536DGKR | ⇒ PCD80725EL/F | ↔ PI5C16292AX | ⇒ PMP5501G |
| ⊖ R5F211B4D61SP | ⊕ SBRT15U50SP5 | ↔ SDH72R12P | ⇒ SI6968EDQ-T1-REVA | ⇒ SL1002A230C |
| ⊕ SP336ECY-L | ⊖ STPS20L25CG-TR/1 | ⊕ STR53041 | D STTA1206DI | ⇒ SUM90N06-5m5P |
| ↔ TC7SH08F | ⊕ THS6184RHFRG4 | ⊖ TMP442ADCNTG4 | ⊕ UNR5211G0L/UN5211 | ⇒ VI-J6M-EZ |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited