

	<h2 style="color: red;">DS1818-20</h2>
	<p>Manufacturer Part Number: DS1818-20</p> <p>Manufacturer/Brand: Maxim Integrated</p> <p>Part of Description: IC 2.55V W/PB 20% TO92-3</p> <p>Datasheets: 1.DS1818-20.pdf 2.DS1818-20.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	DS1818-20
Manufacturer	Maxim Integrated
Description	IC 2.55V W/PB 20% TO92-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	EconoReset
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.55V
Packaging	Bulk

DS1818-20 is New Original in Stock, Search DS1818-20 Datasheets, PDF, Inventory at Y-IC.com Online, Order DS1818-20 Maxim Integrated with warrantied and confidence. RFQ DS1818-20 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>DS1818-10+ Maxim Integrated IC 2.88V W/PB 10% TO92-3</p>	 <p>DS1818-20+ Maxim Integrated IC 2.55V W/PB 20% TO92-3</p>	 <p>DS1818-20/T&R Maxim Integrated IC 2.55V W/PB 20% TO92-3</p>	 <p>DS1818-10/T&R Maxim Integrated IC 2.88V W/PB 10% TO92-3</p>
 <p>DS1818-10+T&R Maxim Integrated IC 2.88V W/PB 10% TO92-3</p>	 <p>DS1818-10/TR DALLAS DS1818-10/TR DALLAS</p>	 <p>DS1818-5 Maxim Integrated IC 3.06V W/PB 5% TO92-3</p>	 <p>DS1818-20+T&R Maxim Integrated IC 2.55V W/PB 20% TO92-3</p>

Hot Parts

More

- | | | | | |
|-------------------|------------------------|--------------------|-------------------|------------------------|
| ⚙️ 1808AA140JAT1A | ➡️ 2MBI100U2A-060-50 | ➡️ ACPM-7500-TC1 | D ADP3338AKCZ-5R7 | ➡️ ADS54T04IZAYR |
| ⚡️ AT24C164-SI-B | ⚙️ C2012C0G2A153K085AC | D CAT9552YI | ➡️ CY7B991V-5JC | ➡️ DD30GB160 |
| ⚙️ DD40F-160 | ⚡️ DS1746W-120IND+ | ⚙️ FCA76N60NF | ➡️ FJA42130TU | ➡️ GRM1555C1H3R7CZ01D |
| D H11A3FR2M | ⚙️ HMHA2801R2 | ⚡️ HV7801K1-G | ⚙️ KK3000A800V | ➡️ LC4032V-75TN44C-10I |
| ➡️ LM6154BCM | ➡️ LNK457VG | ⚙️ LT3433IFE#TRPBF | ⚡️ LTST-S271KRKT | ➡️ MAX8855ETJ+T |
| ➡️ MI-J22-IY-03 | ➡️ PA102FDG | D PSCH85/14 | ⚙️ RPM300YA10RJ | ⚡️ S-24CS64AOI-T8T1GE |
| ⚙️ SB30-09J | D SCAN18373TSSCX | ➡️ SH8M12TB | ➡️ SM15T56CA | ➡️ SMBJ78CA-E3/52 |
| ⚡️ TC125301ECTTR | ⚙️ TC74HCT04AFN | ➡️ TL084QDR | ➡️ TL35074AN | ➡️ UC2844AD |
| ⚙️ UdzSTE-1716B | ⚡️ V24C24C100BL3 | ⚙️ VE-J04-EZ | D VI-2T3-EX | ➡️ VI-J20-MZ |
| ➡️ VI-J34-CW | ⚙️ VS-30WQ10FNTR | ⚡️ XN0A312G0L+ | ⚙️ Z8F021ASJ020SC | ➡️ ZW1R52415 |