










| | |
|---|--|
|  <p>Not Actual Photo YIC International Co., Limited.</p> | <h2 style="color: red;">DRCQA44E0L</h2> |
| | <p>Manufacturer Part Number: DRCQA44E0L</p> <p>Manufacturer/Brand: PANASONIC</p> <p>Part of Description: PANASONIC SOD723</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 40500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation. See specs for product details.</p> | |

| Specifications | |
|----------------|--|
| Part Number | DRCQA44E0L |
| Manufacturer | PANASONIC |
| Description | PANASONIC SOD723 |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 40500 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

DRCQA44E0L is New Original in Stock, Search DRCQA44E0L Datasheets, PDF, Inventory at Y-IC.com Online, Order DRCQA44E0L with warrantied and confidence. RFQ DRCQA44E0L : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|---|---|--|---|
|  <p>DRCG-WS01 Essentra Components C-PROFILE RAIL MOUNTING CLIP: UL</p> |  <p>DRC9A43E0L Panasonic TRANS PREBIAS NPN 0.125W SSMINI3</p> |  <p>DRCG-WS01 Essentra Components G-PROFILE RAIL MOUNTING CLIP: UL</p> |  <p>DRCT-WS01 Essentra Components TOP HAT PROFILE RAIL MOUNTING CL</p> |
|  <p>DRCG-SEC01 Essentra Components G-PROFILE RAIL MOUNTING CLIP: UL</p> |  <p>DRC9A44E0L PANASON DRC9A44E0L PANASON</p> |  <p>DRCT-SEC01 Essentra Components TOP HAT PROFILE RAIL MOUNTING CL</p> |  <p>DRCG-LWS01 Essentra Components G-PROFILE RAIL MOUNTING CLIP: UL</p> |

Hot Parts More

- | | | | | |
|-----------------------|-------------------------|---------------------|--------------------|-----------------------|
| ⚙️ 06035C152J4T2A | ➡️ 08055C153K4T2A | ➡️ 12061C332KA12A | D 1812GC202MATME | ➡️ AT25020N-10SA-5.0B |
| ⚡ AT49LV8192A-70TC | ⚙️ B39458-M3575-N301 | D CC0402KRX5R7BB683 | ➡️ CY2308SI-4 | ➡️ DF3A3.3FV |
| ⚙️ DS14C89ATN | ⚡ FAN5093MTC | ⚙️ FQL40N50F | ➡️ HF50ACC321611-T | ➡️ HN58X24512FP1E |
| D KSD986YSTSSTU | ⚙️ LM2679SX-ADJ | ⚡ LP5900SD-2.0 | ⚙️ LPS6225-103MLC | ➡️ LQH31MN5R6K03L |
| ➡️ LT1129IQ-5 | ➡️ MAX907CSA+T | ⚙️ MC33897EF/R2 | ⚡ MCIMX27VOP4A | ➡️ MCR03EZPJ361 |
| ➡️ MSM514256C-60JSDR1 | ➡️ MSM51V17405F-50T3-FA | D MT16083800A00 | ⚙️ NCP3063BMNTXG | ⚡ NPRITE0602N75R |
| ⚙️ PMV65ENEA | D PS2566L-4 | ➡️ QRW025A0A41 | ➡️ R350SH10 | ➡️ SGL41-60-E3/96 |
| ⚡ SI9933BDY-T1-E3 | ⚙️ SN65C3221EDBR | ➡️ SN74HCT02DR | ➡️ SPHE8202PQ | ➡️ SQ4936EY-T1-GE3 |
| ⚙️ STW13NM50N | ⚡ TDA7490L | ⚙️ TISP8200HDMR-S | D TLV1117-50CKVUR | ➡️ TPS57140QDGQRQ1 |
| ➡️ TPS61188 | ⚙️ TSX923IST | ⚡ UPD485505G-25 | ⚙️ VS-80CPH03-F3 | ➡️ ZP3000A1600V |