


	<p>MC68HC000FN16R2</p>
	<p>Manufacturer Part Number: MC68HC000FN16R2</p> <p>Manufacturer/Brand: NXP Semiconductors / Freescale</p> <p>Part of Description: IC MPU M680X0 16MHZ 68PLCC</p> <p>Datasheets:  MC68HC000FN16R2.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	MC68HC000FN16R2
Manufacturer	NXP Semiconductors / Freescale
Description	IC MPU M680X0 16MHZ 68PLCC
Category	Integrated Circuits (ICs) > Embedded - Microprocessors
Part Status	Require For Quote & Check Stock
Series	M680x0
Operating Temperature	0°C ~ 70°C (TA)
Package / Case	68-LCC (J-Lead)
Supplier Device Package	68-PLCC (25x25)
Core Processor	EC000
Speed	16MHz
Ethernet	-
USB	-
Voltage - I/O	5.0V
Number of Cores/Bus Width	1 Core, 32-Bit
Co-Processors/DSP	-
RAM Controllers	-
Graphics Acceleration	No
Display & Interface Controllers	-
SATA	-
Security Features	-
Additional Interfaces	-
Packaging	Tape & Reel (TR)

MC68HC000FN16R2 is New Original in Stock, Search MC68HC000FN16R2 Datasheets, PDF, Inventory at Y-IC.com Online, Order MC68HC000FN16R2 NXP Semiconductors / Freescale with warrantied and confidence. RFQ MC68HC000FN16R2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MC68HC000FN12 MOTOROLA MC68HC000FN12 MOTOROLA</p>	 <p>MC68HC000FN8R2 MOT</p>	 <p>MC68HC000FC10 MOTO MC68HC000FC10 MOTO</p>	 <p>MC68HC000FN20 MOTOROR MOTOROR PLCC68</p>
 <p>MC68HC000FN10 MOTOROL MC68HC000FN10 MOTOROL</p>	 <p>MC68HC000FC8-2B89N MOT MC68HC000FC8-2B89N MOT</p>	 <p>MC68HC000IE116 NXP Semiconductors / Freescale IC MPU M680X0 16MHZ 68PLCC</p>	 <p>MC68HC000FN16 NXP Semiconductors / Freescale IC MPU M680X0 16MHZ 68PLCC</p>

Hot Parts

More

- | | | | | |
|------------------------|------------------------|---------------------|-------------------------|-----------------------|
| ⊕ 06033A270K4T2A | ↔ 120782-DD85N | ⇒ 2225HC392MAT1A\SB | D ADC11DL066CIVS | ⇒ AK6514CF |
| ⊖ AMC2442ACV1048 | ⊕ BStM4590 | D C1CB00004298 | ⇒ C2012NP02W101J060AA | ⇒ C3216X7T2W104M160AA |
| ⊕ CGA4F3C0G2E102J085AA | ⊖ CGA6L1X7S3A472K160AA | ⊕ CL10C151GB8NNNC | ↔ CMPSH-3ETR-LF | ⇒ CS4281-CM |
| D DF20CA120 | ⊕ FDMA1028NZ | ⊖ FWC-32A10F | ⊕ GRB12250D-6W-B | ⇒ GRM43DR72J104KW01L |
| ⇒ HA17558AFEL-E-Q | ↔ HUF76639P | ⊕ ICL3237CA-T | ⊖ ISL6207HBZ | ⇒ IXTA36N30P |
| ↔ KSC1845PTA | ⇒ LT1940EFE#TRPBF | D LTC1293DCN | ⊕ MAX232ECWE+ | ⊖ MAX666ESA+T |
| ⊕ MB89259A-PF-G-BND-ER | D MCD95-16IO1 B | ⇒ MP33AB01HTR | ↔ NLV14538BDR2G | ⇒ P080CH12FJ0 |
| ⊖ P200RSE060 | ⊕ PH150F48-12 | ↔ PIC16F1789T-I/MV | ⇒ RT0603BRD073K3 | ⇒ RT9262CS. |
| ⊕ S-T111B25MC-OGK-TF | ⊖ S3P825AXZZ-COCA | ⊕ SBAS16XV2T1G | D SI7806ADN | ⇒ SN74ALS1004DR |
| ↔ SY100EL91ZI | ⊕ TAJT106K010RNJ | ⊖ TLV2221IDBVRG4 | ⊕ UDZSTE-1715B/0805-15V | ⇒ WG82567V-SLAW5 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited