

 Not Actual Photo YIC International Co., Limited.	MLX90285LVK-AAA-000-SP
	Manufacturer Part Number: MLX90285LVK-AAA-000-SP Manufacturer/Brand: Melexis Part of Description: IC MOTOR DRIVER PAR TO92-4 RoHs Status:  Lead free / RoHS Stock Condition:  New original, Stock Available. Ship From: Hong Kong Shipment Way: DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	MLX90285LVK-AAA-000-SP
Manufacturer	Melexis
Description	IC MOTOR DRIVER PAR TO92-4
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	-
Technology	-
Operating Temperature	-40°C ~ 150°C (TJ)
Mounting Type	Through Hole
Interface	Parallel
Applications	Fan Motor Driver
Package / Case	TO-226-4, TO-92-4
Supplier Device Package	TO-92-4 (flat)
Voltage - Supply	5 V ~ 30 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	350mA
Output Configuration	High Side (2)
Voltage - Load	5 V ~ 30 V
Motor Type - Stepper	-
Motor Type - AC, DC	Brushless DC (BLDC)
Step Resolution	-
Packaging	Bulk

MLX90285LVK-AAA-000-SP is New Original in Stock, Search MLX90285LVK-AAA-000-SP Datasheets, PDF, Inventory at Y-IC.com Online, Order MLX90285LVK-AAA-000-SP Melexis with warrantied and confidence. RFQ MLX90285LVK-AAA-000-SP : Info@Y-IC.com

You May Be Also Be interested

In:

 MLX90287LZC-AAA-000-RX MELEXIS MLX90287LZC-AAA-000-RX MELEXIS	 MLX90277FA MELEXIS MLX90277FA MELEXIS	 MLX90285LVK-ABA-000-SP Melexis IC MOTOR DRIVER PAR TO92-4	 MLX90279BA MELEXIS MLX90279BA MELEXIS
 MLX90277F MELEXIS MLX90277F MELEXIS	 MLX90287LLD-AAA-000-SP Melexis IC MOTOR DRIVER PWM 10DFN	 MLX90287LZC-AAA-000-SP Melexis IC MOTOR DRIVER PWM 8SOIC	 MLX90277-EGO-FA-SPECIFIC MELEXIS MELEXIS TSSOP14

Hot Parts

More

- | | | | | |
|--------------------|----------------------|----------------------|----------------------|-------------------|
| ⊛ 08051U9R1BAT2A | ↔ 08053C105MAT2A | ⇒ 1206YA222FAT2A | D AD116S10KCF | ⇒ AD5241BRZ10 |
| ⊣ AN32122A-PR | ⊛ B22B-PHDSS | D BSV52RTA | ⇒ CC1140-A | ⇒ CD143A-SR70 |
| ⊛ CMM6004G-SC-0G0M | ⊣ CPH5503-TL-E | ⊛ CST5206A18TR | ↔ DC09-73LF | ⇒ DP15F600T101628 |
| D DRV5013ADQLPGM | ⊛ DT104N10KOF | ⊣ DZ540N04K | ⊛ EMK212BJ475MG-T | ⇒ FDD6680A-NL |
| ⇒ G6QE2G595N2EJ-J | ↔ GJM0225C1E100JB01L | ⊛ GRM0335C1H560JA01J | ⊣ GRM1555C1H7R3CZ01D | ⇒ ISL6150IB-T |
| ↔ KNA16150C33MA7TS | ⇒ LA1837ML-MIT-TLM-E | D MCP101450DI | ⊛ MDCA0418EURH | ⊣ MIC94310-NYCSTR |
| ⊛ OP282GPZ | D OPA4343UA/2K5 | ⇒ PHP129NQ04LT | ↔ PM8389-NI | ⇒ RM500CZ-H |
| ⊣ RT0603BRE0749R9 | ⊛ SA52620703 | ↔ SD103CW-V-GS08 | ⇒ SI1406DH | ⇒ SI3442DV-T1 |
| ⊛ SI6969DQ-T1-E3 | ⊣ SR100L-8S | ⊛ SST12LN01-QU6F | D STGY40NC60V | ⇒ TK11245CMTL |
| ↔ TPS73230DBVRG4 | ⊛ V24C12M100BN | ⊣ VE-J71-CZ | ⊛ VNQ500PA | ⇒ WG14016FR02 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited