


	<p>Manufacturer Part Number: HD9P6409-9Z96</p>
	<p>Manufacturer/Brand: Intersil</p>
	<p>Part of Description: IC MED MANCHESTER 1MHZ 20-SOIC</p>
	<p>Datasheets:  HD9P6409-9Z96.pdf</p>
<p>RoHS Status:  Lead free / RoHS</p>	<p>Stock Condition: Compliant New original, 3 pcs Stock Available.</p>
<p>Ship From: Hong Kong</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	HD9P6409-9Z96
Manufacturer	Intersil
Description	IC MED MANCHESTER 1MHZ 20-SOIC
Category	Integrated Circuits (ICs) > Specialized ICs
Part Status	3 pcs Stock
Series	-
Mounting Type	Surface Mount
Type	Manchester Encoder/Decoder
Applications	Security
Package / Case	20-SOIC (0.295", 7.50mm Width)
Supplier Device Package	20-SOIC
Packaging	Tape & Reel (TR)

HD9P6409-9Z96 is New Original in Stock, Search HD9P6409-9Z96 Datasheets, PDF, Inventory at Y-IC.com Online, Order HD9P6409-9Z96 Intersil with warrantied and confidence. RFQ HD9P6409-9Z96 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>HD9P6409-9 INTERSIL HD9P6409-9 INTERSIL</p>	 <p>HD99 Vector Electronics & Technology, Inc. HARDWARE KIT M2.5 X 11MM SLEEVE</p>	 <p>HD970040D HITACHI HD970040D HITACHI</p>	 <p>HD9P6409-9Z Intersil IC MED MANCHESTER 1MHZ 20-SOIC</p>
 <p>HD965-R2 HSMC HD965-R2 HSMC</p>	 <p>HD99-1 Vector Electronics & Technology, Inc. HARDWARE KIT M2.5 X 11MM SLEEVE</p>	 <p>HD970 PTC HD970 PTC</p>	 <p>HD9601F-T2 FOXCONN HD9601F-T2 FOXCONN</p>

Hot Parts

More

- | | | | | |
|-----------------------|-------------------------|----------------------|--------------------------|-----------------------|
| ⊕ 0805YC333KAT2A | ↔ 12061C333KAT2M | ⇒ 18125G105ZAT2A | D ACPL-217-500E | ⇒ AD7237JR |
| ⊖ AP138-30WA | ⊕ B39202-B7846-K410-S09 | D BD9E151NUX | ⇒ BZX84C3V9LT1G | ⇒ C1005X5R1E105M050BC |
| ⊕ C2012NP01H272J060AA | ⊖ CGA2B2C0G2A181J050BA | ⊕ CP0603A1880LNTR | ↔ CXT5551ETR | ⇒ FGA30S120P |
| D GQM1555C2A360FB01D | ⊕ GQM1555C2D4R5CB01D | ⊖ GRM1555C2A6R1CA01J | ⊕ GRM2166T1H241JD15D | ⇒ ISL3232ECV-16Z |
| ⇒ LK112M32TR | ↔ LM21212MH-1/NOPB | ⊕ LT1636CMS8#TRPBF | ⊖ LTC4150CMS#PBF | ⇒ LTST-C230TBKT |
| ↔ LTV-356T-TP1-BC | ⇒ M16P152J/9514 | D MAX4521CSE | ⊕ MAX6336US23D3-T | ⊖ MAX9181EXT-T |
| ⊕ MC14557BAL | D MIC59300-1.2YME | ⇒ MLG1005S27NJTD07 | ↔ N370SH12 | ⇒ NJM2113V |
| ⊖ PBRC2.00HR50X000 | ⊕ PGB0040805MR | ↔ PIC18F66J16-I/PT | ⇒ PMBZ5230B | ⇒ QYD25GC2415D |
| ⊕ RT9231ACS | ⊖ SBRT3M40P1-7 | ⊕ SFH610A-3X007 | D SG-8002CA125.000000MHZ | ⇒ SMBJ14CA |
| ↔ SMBJ250A | ⊕ SRR0604-101ML | ⊖ TIP30ATU | ⊕ TN5325N3-G | ⇒ YFF21SC1E473MT009N |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited