


	<p>S-8209AAY-T8T1U</p>
	<p>Manufacturer Part Number: S-8209AAY-T8T1U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC BATT MFUNC LI-ION 8TSSOP</p>
	<p>Datasheets:  S-8209AAY-T8T1U.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	S-8209AAY-T8T1U
Manufacturer	SII Semiconductor Corporation
Description	IC BATT MFUNC LI-ION 8TSSOP
Category	Integrated Circuits (ICs) > PMIC - Battery Management
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Battery Chemistry	Lithium-Ion/Polymer
Number of Cells	-
Interface	-
Package / Case	8-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	8-TSSOP
Function	Multi-Function Controller
Fault Protection	-
Packaging	Tape & Reel (TR)

S-8209AAY-T8T1U is New Original in Stock, Search S-8209AAY-T8T1U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-8209AAY-T8T1U SII Semiconductor Corporation with warrantied and confidence. RFQ S-8209AAY-T8T1U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-8209AAW-T8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION 8TSSOP</p>	 <p>S-8209AB0-T8T1U SEIKO SEIKO TSSOP</p>	 <p>S-8209ABC-T8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION 8TSSOP</p>	 <p>S-8209AAU-I8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION SNT-8A</p>
 <p>S-8209AAX-I8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION SNT-8A</p>	 <p>S-8209AAV-T8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION 8TSSOP</p>	 <p>S-8209AAT-T8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION 8TSSOP</p>	 <p>S-8209AAZ-I8T1U SII Semiconductor Corporation IC BATT MFUNC LI-ION SNT-8A</p>

Hot Parts

More

- | | | | | |
|-------------------|----------------------|----------------------|-----------------------|--------------------|
| ⊛ 06031A220J4T2A | ↔ 08055C104JAT2P | ⇒ 12061C472JAT2A | D 1808HA330KAT1A | ⇒ B130L-13-F |
| ⊣ BD3561BFP-CE2 | ⊛ BD8119FF | D BSP318SL6327 | ⇒ C5750X7R2A335K230KA | ⇒ CL21B106KQNNNF |
| ⊛ CL21C300KBANNNC | ⊣ CM8870PI | ⊛ CY7C261-25JC | ↔ DD540N22K | ⇒ DZT5401-13 |
| D FZT951QTA | ⊛ GRM1555C1H470FA01J | ⊣ GRM32NR72A104KA01 | ⊛ HA17358BRP | ⇒ IRFH8311TRPBF. |
| ⇒ ISL6314IRZ | ↔ LM2585SX-ADJ | ⊛ LM27289SQ | ⊣ LM4040CIZ-10 | ⇒ LMS1585AIS-3.3 |
| ↔ M24C04-MN6 | ⇒ MAX4586EUB+T | D MBRS140T3 | ⊛ MC145453P | ⊣ MG100N2YS3 |
| ⊛ MIC22601YML | D N600DH15HOO | ⇒ NLC322522T-150K-PF | ↔ PH100S48-28 | ⇒ PK110F80 |
| ⊣ PM75CLS060 | ⊛ RT9818F-20PVL | ↔ S-814B37AMC-BER-T2 | ⇒ S2210R01 | ⇒ SFH6705-X007 |
| ⊛ SP232AEP-L | ⊣ STM8S903F3M3TR | ⊛ T468S16NL | D TDA8929T | ⇒ TISP4S088M3BJR-S |
| ↔ TJA1054T/VM | ⊛ UC2524DW | ⊣ VI-25Y-IX | ⊛ XC6209F332PR | ⇒ YPPD-J010AF |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited