


 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">ADA4084-2ARMZ-REEL7</h2>
	<p>Manufacturer Part Number: ADA4084-2ARMZ-REEL7</p> <p>Manufacturer/Brand: AD</p> <p>Part of Description: AD MSOP8</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 1900 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	ADA4084-2ARMZ-REEL7
Manufacturer	AD
Description	AD MSOP8
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1900 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

ADA4084-2ARMZ-REEL7 is New Original in Stock, Search ADA4084-2ARMZ-REEL7 Datasheets, PDF, Inventory at Y-IC.com Online, Order ADA4084-2ARMZ-REEL7 with warrantied and confidence. RFQ ADA4084-2ARMZ-REEL7 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ADA4084-2ACPZ-RL ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8LFCSP</p>	 <p>ADA4084-2ARZ-R7 ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8SOIC</p>	 <p>ADA4084-2ACPZ-R7 ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8LFCSP</p>	 <p>ADA4084-1ARZ-RL ADI (Analog Devices, Inc.) IC OP AMP RRIO 30V SGL 8-SOIC</p>
 <p>ADA4084-2ARZ-RL ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8SOIC</p>	 <p>ADA4084-2ARMZ-RL ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8MSOP</p>	 <p>ADA4084-4ACPZ-R7 ADI (Analog Devices, Inc.) IC OPAMP RRIO 30V QUAD 16LFCSP</p>	 <p>ADA4084-2ARMZ-R7 ADI (Analog Devices, Inc.) IC OPAMP GP 15.9MHZ RRO 8MSOP</p>

Hot Parts

More

- | | | | | |
|---------------------|-------------------------|----------------------|------------------------|------------------------|
| ⚙️ 12065C682KAT2A | ➡️ 16FL100S10 | ➡️ ADUM1300WTRWZ | D BAR63-02VH6327 | ➡️ BAR90-02ELS |
| ⚡️ BCM1113RKP | ⚙️ BK1608LL431-T | D C1005JB1E103K050BA | ➡️ C1608C0G2A471K080AA | ➡️ C4532X5R1A476M280KA |
| ⚙️ C90-101-0004 | ⚡️ CGA2B2X8R1H151M050BA | ⚙️ CL10C240JB8NNND | ➡️ DAC8512FS | ➡️ FSDH565RN |
| D HLMP-1301-E00A2 | ⚙️ HNC-05LX | ⚡️ ICS8633AF-01LFT | ⚙️ IDD-0512 | ➡️ IRLS620A |
| ➡️ ISL99227IRZ-T | ➡️ IXSH30N60U1 | ⚙️ K4S2808320-TC75 | ⚡️ LM5080MM | ➡️ LMSP33AA-262 |
| ➡️ LTC3784EUFDP#PBF | ➡️ MC34118EGR3 | D MCT2201300 | ⚙️ MX7226KCWP | ⚡️ NC7SZ125M5X |
| ⚙️ NNCD11F-T1B | D NTSJ2080CTG | ➡️ P4SMA11A-E3/61 | ➡️ P589A-A41-PM | ➡️ PCA82C251. |
| ⚡️ PM20EF060-32 | ⚙️ PS399CSEX | ➡️ PVZ3A502A01R02 | ➡️ SD25-0836R9UBQ2 | ➡️ SKIM501GD063DM |
| ⚙️ SM3005NSF | ⚡️ SN75110AD | ⚙️ SSTUF32865AHLFT | D ST62T55BM6 | ➡️ STK402-920 |
| ➡️ SV28-5-150-5P | ⚙️ V24C24T100AL | ⚡️ V300B3V3H150A | ⚙️ VI-2N3-11 | ➡️ VI-2WN-EV |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited