

 <p>Not Actual Photo YIC International Co., Limited.</p>	<p>1825CC473MAZ1A</p> <p>Manufacturer Part Number: 1825CC473MAZ1A</p> <p>Manufacturer/Brand: AVX</p> <p>Part of Description: 1825CC473MAZ1A AVX</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 347 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	<p>Image may be representation. See specs for product details.</p>

Specifications

Part Number	1825CC473MAZ1A
Manufacturer	AVX
Description	1825CC473MAZ1A AVX
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	347 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

1825CC473MAZ1A is New Original in Stock, Search 1825CC473MAZ1A Datasheets, PDF, Inventory at Y-IC.com Online, Order 1825CC473MAZ1A with warrantied and confidence. RFQ 1825CC473MAZ1A : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>1825CC562KAT1A AVX Corporation CAP CER 5600PF 630V X7R 1825</p>	 <p>1825CC683JAT1A AVX Corporation CAP CER 0.068UF 630V X7R 1825</p>	 <p>1825CC473MAT9A AVX Corporation CAP CER 0.047UF 630V X7R 1825</p>	 <p>1825CC473MAT3A\SB AVX Corporation CAP CER 0.047UF 630V X7R 1825</p>
 <p>1825CC473MAT1A\SB AVX Corporation CAP CER 0.047UF 630V X7R 1825</p>	 <p>1825CC473MAT1A AVX Corporation CAP CER 0.047UF 630V X7R 1825</p>	 <p>1825CC564KAT2A AVX Corporation CAP CER 0.56UF 630V X7R 1825</p>	 <p>1825CC562KAT1A\SB AVX Corporation CAP CER 5600PF 630V X7R 1825</p>

Hot Parts More

- | | | | | |
|---------------------|-------------------|-----------------------|-------------------|-----------------------|
| ⚙️ 0402YC183MAT2A | ➡️ 2MBI200NR060 | ➡️ A8292SETTR-T | D AP4310AMTR-G1 | ➡️ B39931-B4063-U810 |
| ⚡️ BD2606MVV-E2 | ⚙️ C0402C0G1C3R6C | D CL21C100JC61PNC | ➡️ CPH5808-TL-E | ➡️ CRCW25122R00JNEG |
| ⚙️ DB1025BA | ⚡️ DDZ9707-7 | ⚙️ DF30NA160 | ➡️ DG444BDY | ➡️ DT1608C-472B |
| D FDS6898AZ_F085 | ⚙️ FW82541PI | ⚡️ GRM0222C1C4R7CD05D | ⚙️ HEF4044BT | ➡️ IRKTF72-08 |
| ➡️ KK90F-120 | ➡️ LQG15HN2N4S02D | ⚙️ M74HCT652B1R | ⚡️ MAX4220ESD-T | ➡️ MM3243ARRE |
| ➡️ MNR02MOAJ223-22K | ➡️ MSM80C88A-2JS | D MTD002-LF-00 | ⚙️ NJM064VC-TE1 | ⚡️ NRF24LE1-O17Q48-R7 |
| ⚙️ PA1314NLT | D RSS085N05TB | ➡️ S29JL032H70TFI210H | ➡️ SKN20/06UNF | ➡️ SKT130/14E |
| ⚡️ SN74CBT6800CPWR | ⚙️ SN74S20N | ➡️ SPX29151T5-3.3 | ➡️ SUP85N02-03-E3 | ➡️ T281N65TOF |
| ⚙️ TC621HCOA | ⚡️ TM130EZ-2H | ⚙️ TMP8085AHP-2 | D TSM1A103F34D1R | ➡️ TT81N120KOC |
| ➡️ UPA671T-T1-A | ⚙️ VE-260-IU | ⚡️ VI-B6Y-CV | ⚙️ VS-MUR820PBF | ➡️ XP131A0232SR |