

	<p><b>MIC2774H-31BM5-TR</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">MIC2774H-31BM5-TR</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Micrel / Microchip Technology</a></p> <p><b>Part of Description:</b> IC SUPERVISOR DUAL LV SOT23-5</p> <p><b>Datasheets:</b>  <a href="#">MIC2774H-31BM5-TR.pdf</a></p> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <p><b>Stock Condition:</b> New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	<a href="#">MIC2774H-31BM5-TR</a>
Manufacturer	<a href="#">Micrel / Microchip Technology</a>
Description	IC SUPERVISOR DUAL LV SOT23-5
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Complementary
Reset	Active High
Number of Voltages Monitored	2
Reset Timeout	140 ms Minimum
Voltage - Threshold	3.09V, Adj
Packaging	Tape & Reel (TR)

MIC2774H-31BM5-TR is New Original in Stock, Search MIC2774H-31BM5-TR Datasheets, PDF, Inventory at Y-IC.com Online, Order MIC2774H-31BM5-TR Micrel / Microchip Technology with warrantied and confidence. RFQ MIC2774H-31BM5-TR : [Info@Y-IC.com](mailto:Info@Y-IC.com)























### You May Be Also Be interested

In:

 <p><b>MIC2774H-44YM5-TR</b> Micrel / Microchip Technology IC SUPERVISOR DUAL LV SOT23-5</p>	 <p><b>MIC2774H-44BM5 TR</b> MIC MIC SOT23-5</p>	 <p><b>MIC2774H-31BM5 TR</b> MICERL MICERL SOT23-5</p>	 <p><b>MIC2774H-31YM5-TR</b> Micrel / Microchip Technology IC SUPERVISOR DUAL LV SOT23-5</p>
 <p><b>MIC2774H-44BM5-TR</b> Micrel / Microchip Technology IC SUPERVISOR DUAL LV SOT23-5</p>	 <p><b>MIC2774H-29BM5-TR</b> Micrel / Microchip Technology IC SUPERVISOR DUAL LV SOT23-5</p>	 <p><b>MIC2774H-44BM5</b> MIC MIC SOT23-5</p>	 <p><b>MIC2774H-29YM5-TR</b> Micrel / Microchip Technology IC SUPERVISOR DUAL LV SOT23-5</p>

### Hot Parts

[More](#)

- |  |  |   |   |  |
|--|--|---|---|--|
|  06035A271JAT2A     |  08055C103KAT2M     |  12065C274JAT2A  |  ACH3218-151-TD01     |  AD704TQ/883B       |
|  AD7414ART-0REEL7   |  AN78L08M-E1        |  B40D100L        |  C0402C0G1C620G       |  C1005CH2A821K050BC |
|  C2012JB1A106K125AC |  C90-101-0004       |  CCK-0512DF      |  CGA3E2C0G2A1R5C080AA |  CXA1522N-T4        |
|  DSA15IM200UC       |  E74HA2.2B-G        |  FDPF5N50NZF     |  GP1UXC21QS           |  GQM1555C2DR60CB01D |
|  GRM0335C1H1R6BD01D |  GRM1555C1E6R7CZ01D |  HMC226TR        |  IDT74FCT162373TPV    |  IRKH132/04         |
|  IRL3714Z           |  IXBH16N170         |  KTC3195Y        |  LQH31MN2R7J03L       |  LT1761ES5-3TRMPBF  |
|  LT5504EMS8#PBF     |  MA27V1500L         |  MASWSS0039TR    |  MAX4400AXK-T         |  MM74HCT273SJ       |
|  MMBT2222AT1G       |  NJG1128HB6         |  NSBC143ZPDXV6T5 |  RN296PFS             |  SD85N12P           |
|  SKIIP30NAC12IT42   |  SM6T68CA-TR        |  SN74LVC2244APWR |  T2159N22TOF          |  TMP121AIDBVRG4     |
|  TS1001IJ5T         |  TZB4Z030AA10R00    |  UC3524DW        |  UDZ6V2B-7-F          |  VI-223-IY          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited