

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">2SD601A-Q</h2>
	<p><b>Manufacturer Part Number:</b> 2SD601A-Q</p> <p><b>Manufacturer/Brand:</b> PANASON</p> <p><b>Part of Description:</b> PANASON SOT-23</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 183300 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	2SD601A-Q
Manufacturer	PANASON
Description	PANASON SOT-23
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	183300 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

2SD601A-Q is New Original in Stock, Search 2SD601A-Q Datasheets, PDF, Inventory at Y-IC.com Online, Order 2SD601A-Q with warranted and confidence. RFQ 2SD601A-Q : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>2SD601A</b> Original SOT-23</p>	 <p><b>2SD601A(TX)</b> PANASONIC PANASONIC SOT-23</p>	 <p><b>2SD601A-(TX)</b> Panason Panason SOT-23</p>	 <p><b>2SD601A-R(TW)</b> PANASONIC PANASONIC 3kreel</p>
 <p><b>2SD601-R(TX)</b> Panason Panason SOT23</p>	 <p><b>2SD601A-Q(TX)+</b> Panason Panason SOT-23</p>	 <p><b>2SD601A-Q TX</b> PANASON PANASON SOT-23</p>	 <p><b>2SD601A-R</b> PANASON PANASON SOT-23</p>

### Hot Parts More

- |                   |                      |                       |                      |                     |
|-------------------|----------------------|-----------------------|----------------------|---------------------|
| ⚙️ 1808HA330KAT1A | ➡️ AK1502A-L         | ➡️ AP1117VC-TRL       | D AVRL101A1R1NTB     | ➡️ BF1210Y33        |
| ⊖ BstQ63120       | ⚙️ BZB784-C6V2       | D C2012X5R2A683M085AA | ➡️ CD74HC374M96      | ➡️ CLF6045T-151M-CA |
| ⚙️ ESH2PDHM3/84A  | ⊖ GCM1885G1H331JA16D | ⚙️ GRM0335C2A8R3DA01J | ➡️ HFA80FA120P       | ➡️ HNC-050P         |
| D IRF7521D1TRPBF  | ⚙️ IRFK4J450         | ⊖ IRGB4061D           | ⚙️ ISL28133FHZ-T7    | ➡️ ISL88031IU8ECZ   |
| ➡️ IXGH30N60B     | ➡️ LD2980CM50        | ⚙️ LE25FW056CS        | ⊖ LQP02TQ3N9B02D     | ➡️ MAX2373EGC+T     |
| ➡️ MCC170-16I01   | ➡️ MMBT2222A         | D MURS160/5           | ⚙️ N105PH14          | ⊖ N350CH15G00       |
| ⚙️ NE02130-T1-A   | D PC901V0YSZXF       | ➡️ PMB6725XFV1.521    | ➡️ POWERV0.4         | ➡️ QM100TX-HB       |
| ⊖ RGF1G-E3/5CA    | ⚙️ RT9194CE          | ➡️ SC431LCSK-1        | ➡️ SFH897AS101       | ➡️ SI4100DY-T1-GE3  |
| ⚙️ SJPJ-L3VR      | ⊖ SKT630/16C         | ⚙️ SMP80MC-270        | D SN74CBTLV3245ADBQR | ➡️ STF202-22T1G     |
| ➡️ STS6PF30L      | ⚙️ TDA9887TS         | ⊖ US91AEVK-AAA-000-BU | ⚙️ VI-J61-CY-04      | ➡️ VI-JN1-IY        |