


 life.augmented	TS836-4IZT
	Manufacturer Part Number: TS836-4IZT
 Not Actual Photo YIC International Co., Limited.	Manufacturer/Brand: STMicroelectronics
	Part of Description: IC SUPERVISOR VOLT RESET TO-92
Image may be representation. See specs for product details.	Datasheets:  TS836-4IZT.pdf
	RoHS Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	TS836-4IZT
Manufacturer	STMicroelectronics
Description	IC SUPERVISOR VOLT RESET TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	TO-226-3, TO-92-3 (TO-226AA) (Formed Leads)
Supplier Device Package	TO-92-3
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	20 µs Typical Response Time
Voltage - Threshold	4.5V
Packaging	Tape & Reel (TR)

TS836-4IZT is New Original in Stock, Search TS836-4IZT Datasheets, PDF, Inventory at Y-IC.com Online, Order TS836-4IZT STMicroelectronics with warrantied and confidence. RFQ TS836-4IZT : Info@Y-IC.com

You May Be Also Be interested

In:

 TS836-4IPT STMicroelectronics IC SUPERVISOR VOLT RESET 8-TSSOP	 TS83C51RC2DJT-MCED TEMIC TEMIC QFP	 TS836-4ID STMicroelectronics IC SUPERVISOR VOLT RESET 8-SO	 TS83C51RC2-MC TEMIC TEMIC QFP
 TS83C51RC2DLL-MCB ATMEL ATMEL PLCC44	 TS83C51RC2-MCB ATMEL ATMEL PLCC44	 TS836-4IZ-AP STMicroelectronics IC SUPERVISOR VOLT RESET TO-92	 TS83C51RB2-MA TEMIC TEMIC TQFP44

Hot Parts

More

- | | | | | |
|--------------------------|------------------------|-------------------|--------------------|-----------------------|
| ⚙️ 12065A270JAT2A | ➡️ ACE2302BBM+H | ➡️ AD8667ARZ-REEL | D ADA4431-1YCPZ-R7 | ➡️ AP8853-12PC |
| ⚡ AT93C66PI | ⚙️ AZ34063UP-G1 | D B40CL120S02 | ➡️ BR24T256FJ-WE2 | ➡️ CD74HC132M96 |
| ⚙️ CD90-V5551-1ETR | ⚡ CGA8N3X7S2A475K230KB | ⚙️ CM431LCCM233TR | ➡️ DS1230Y-150+ | ➡️ DS96F173MJ |
| D FAR-F5KB-836M50-B4ER-Z | ⚙️ FDD6676-NL | ⚡ FI168K169706-T | ⚙️ FRS400DA100 | ➡️ GRM1556S1H7R6CZ01D |
| ➡️ GRM1887U1H392JA01J | ➡️ GRM31A5C2J561JW01D | ⚙️ H1164NLT | ⚡ HLMP-6505-L0011 | ➡️ IRFH7923TRPBF. |
| ➡️ IRLS630A | ➡️ LC4512V-75TN176C | D LDC2114YFDR | ⚙️ LQH3NPN4R7NGOK | ⚡ MAX6897PALT+T |
| ⚙️ MC74HC4053ADWG | D NCP4686DSN12T1G | ➡️ PS9636-A | ➡️ R5F3650KCNFB | ➡️ RFDIP1608060T1T |
| ⚡ S-1131B27PD-N4M-TF | ⚙️ SK71GB065TF | ➡️ SM25JZ41 | ➡️ SM5S33AHE3/2D | ➡️ SS15-E3/5AT |
| ⚙️ STF701.TC | ⚡ STP8N65M5 | ⚙️ THS4281DGKR | D TMP125AIDBVR | ➡️ TPS65071A3RSLR |
| ➡️ UNR921NGOL+ | ⚙️ UPA1716G-E1-A | ⚡ W4307ZD240 | ⚙️ XC6375A213PR | ➡️ ZVN4106FTA |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited