


| | |
|---|---|
|  | <p>2SK608</p> |
| | <p>Manufacturer Part Number: 2SK608</p> <p>Manufacturer/Brand: PANASONIC</p> <p>Part of Description: PANASONIC SOT-23</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 3500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation. See specs for product details.</p> | |

Specifications

| | |
|--------------|---|
| Part Number | 2SK608 |
| Manufacturer | PANASONIC |
| Description | PANASONIC SOT-23 |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 3500 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

2SK608 is New Original in Stock, Search 2SK608 Datasheets, PDF, Inventory at Y-IC.com Online, Order 2SK608 with warrantied and confidence. RFQ 2SK608 : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|---|---|--|---|
|  <p>2SK612-Z-E2 NEC NEC TO-252</p> |  <p>2SK611 N N TO-252</p> |  <p>2SK612 NEC NEC TO252</p> |  <p>2SK601-1Y PANASOI PANASOI SOT223</p> |
|  <p>2SK601-TX PANASON PANASON SOT89</p> |  <p>2SK601 P P SC-62</p> |  <p>2SK6042 Original TO-252</p> |  <p>2SK601-(TX) PANASONIC PANASONIC SOT89</p> |

Hot Parts

More

- | | | | | |
|----------------------|----------------------|-----------------------|-----------------------|-------------------|
| ⊛ 08051U2R7BAT4A | ➔ 1808AC102KA13A | ➔ ADR5044AKSZ-REEL7 | D AFP3401SS23RG | ➔ AN41919A-VB |
| ⊣ B7-2415D15M | ⊛ BAT54A-7-F-89 | D BD1090CS_L2_00001 | ➔ BTB16-600SWRG | ➔ CM450DX1-24A |
| ⊛ CPH6121-TL-E | ⊣ CY28325PVC-2 | ⊛ CY7C1313BV18-250BZC | ➔ FDMS7670 | ➔ FP15R06YE3-B4EN |
| D GRM0225C1E5R0BDAEL | ⊛ GRM1885C2A2R5CA01D | ⊣ GRM2197U1H162JZ01D | ⊛ HFC0300HS-C429-LF-Z | ➔ IPP07N60C2 |
| ➔ LG226D104MAT2S1 | ➔ LGA10C-00SADJJ | ⊛ LT1612EMS8#TRPBF | ⊣ LTC3217EUD#PBF | ➔ MAX701CSA |
| ➔ MBRX160-T | ➔ MC79M15CTG | D MCC255-08IO8 | ⊛ MCP3905A-E/SS | ⊣ MP3420ER |
| ⊛ NCV1117DT33RKG | D P087A2004 | ➔ PE40F-120 | ➔ PT5109E23E-28 | ➔ QVE00832C |
| ⊣ R1LV0408DSA-5SI#S0 | ⊛ RB068L100TF | ➔ RFP30N06LE | ➔ RKZ18AKUP6 | ➔ S9S08AW8AEOMLD |
| ⊛ SF3004PTCO | ⊣ SN54LS09J | ⊛ SP207HBET | D SPX1521M3-5.0 | ➔ T85HFL100 |
| ➔ TDA1870A | ⊛ TISP3080H3SL | ⊣ TLV70015DCKR | ⊛ TSHA5202 | ➔ V18MLE0402NH |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited