













| | |
|--|---|
|  <p>A Renesas Company</p> | <p>ISL88002IE16Z-TK</p> |
| | <p>Manufacturer Part Number: ISL88002IE16Z-TK</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC VOLT SUPERVISOR 1.58V SC-70</p> <p>Datasheets:  ISL88002IE16Z-TK.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
|  | |
| <p>Image may be representation. See specs for product details.</p> | |

Specifications

| | |
|------------------------------|--|
| Part Number | ISL88002IE16Z-TK |
| Manufacturer | Intersil |
| Description | IC VOLT SUPERVISOR 1.58V SC-70 |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Type | Simple Reset/Power-On Reset |
| Package / Case | SC-70, SOT-323 |
| Supplier Device Package | SC-70-3 |
| Output | Open Drain or Open Collector |
| Reset | Active Low |
| Number of Voltages Monitored | 1 |
| Reset Timeout | 140 ms Minimum |
| Voltage - Threshold | 1.58V |
| Packaging | Tape & Reel (TR) |

ISL88002IE16Z-TK is New Original in Stock, Search ISL88002IE16Z-TK Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88002IE16Z-TK Intersil with warrantied and confidence.
RFQ ISL88002IE16Z-TK : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|---|--|
| <p>In:</p>  <p>ISL88002IE22Z-T Intersil IC VOLT SUPERVISOR 2.19V SC-70</p> |  <p>ISL88002IE17Z-TK Intersil IC VOLT SUPERVISOR 1.67V SC-70</p> |  <p>ISL88002IE17Z-T7A Intersil IC VOLT SUPERVISOR 1.67V SC70-3</p> |  <p>ISL88002IE22Z-T7A Intersil IC VOLT SUPERVISOR 2.19V SC70-3</p> |
|  <p>ISL88002IE16Z-T7A Intersil IC VOLT SUPERVISOR 1.58V SC70-3</p> |  <p>ISL88001IH46Z-T Intersil IC VOLT SUPERVISOR 4.64V SOT23-3</p> |  <p>ISL88001IH46Z-TK Intersil IC VOLT SUPERVISOR 4.64V SOT-23</p> |  <p>ISL88002IE16Z-T Intersil IC VOLT SUPERVISOR 1.58V SC-70</p> |

Hot Parts

More

| | | | | |
|-----------------------|-------------------|---------------------|-------------------|-----------------|
| 04025C101KAT2A | 06031A330JA4A | 08053C224KAT2A | D 12062A300FAT2A | 12065C272JAT2A |
| 1367645-1 | 1812HA330JAT1A | D 7MBP50RA-060 | AD561JNZ | AD8210YRZ-REEL |
| ADT7485AARMZ | BAT54RALT1 | BT15N120ANTD | BTN7973B | BZX79-C75 |
| D C0603X5R1A334K030BC | C1608X7R1H473K/10 | C2012X7R1H154M085AA | CAT810TTBI-T | CPH3350-TL-W |
| DSEP2X61-04C | FQI13N50 | GRM0336R1E7R2DD01D | IRF6722STR1PBF | IRU1015-33CDTR |
| KTC4377-C | LGC24D225MAT2S1 | LM22675MRX-ADJ/NOPB | LM4809MM/NOPB | M64026FP |
| MCR10EZHZ1R0 | MIC2211-MPBMLTR | NT5TU64M16GG-3C | PMLL4153 | PT6911-S |
| RCLAMP0534N.TCT | S908GR32ACFAE | SGB8206ANT4G | SN74LVTH16373DGGR | SPC5643LF2MMM1R |
| SS14-E3/2GT | SS2060FL | SSQE48T13050NABOG | D STPS30L45CT | TLD1314EL |
| VCO190-395TY | VE-201-EY | VI-251-IX | VOM617A-3T | VUB51-14NO1 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited