










	<p>ISL32496EUIZ</p>
	<p>Manufacturer Part Number: ISL32496EUIZ</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC TXRX 5V RS485 RS422 10MSOP</p> <p>Datasheets:  ISL32496EUIZ.pdf</p> <p>RoHS Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	ISL32496EUIZ
Manufacturer	Intersil
Description	IC TXRX 5V RS485 RS422 10MSOP
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Supplier Device Package	10-MSOP
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Full
Receiver Hysteresis	25mV
Data Rate	15Mbps
Packaging	Tube


























ISL32496EUIZ is New Original in Stock, Search ISL32496EUIZ Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL32496EUIZ Intersil with warrantied and confidence. RFQ
ISL32496EUIZ : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ISL32496EUIZ-T7A Intersil IC TXRX 5V RS485 RS422 10MSOP</p>	 <p>ISL32498EIBZ-T7A Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p>ISL32496EUIZ-T Intersil IC TXRX 5V RS485 RS422 10MSOP</p>	 <p>ISL32496EIBZ Intersil IC TXRX RS485 FAULT PROT 14SOIC</p>
 <p>ISL32498EIBZ Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p>ISL32498EIBZ-T Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p>ISL32495EUIZ-T7A Intersil IC TXRX 5V RS485 RS422 8MSOP</p>	 <p>ISL32496EIBZ-T Intersil IC TXRX RS485 FAULT PROT 14SOIC</p>

Hot Parts

[More](#)

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited