

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">TDA8274AHN/C1518</h2>
	<p>Manufacturer Part Number: TDA8274AHN/C1518</p> <p>Manufacturer/Brand: NXP</p> <p>Part of Description: NXP HVQFN-4</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 25500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	


Specifications

Part Number	TDA8274AHN/C1518
Manufacturer	NXP
Description	NXP HVQFN-4
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	25500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com


TDA8274AHN/C1518 is New Original in Stock, Search TDA8274AHN/C1518 Datasheets, PDF, Inventory at Y-IC.com Online, Order TDA8274AHN/C1518 with warrantied and confidence. RFQ TDA8274AHN/C1518 : Info@Y-IC.com

You May Be Also Be interested


In:




TDA8274AHN/C1,518
NXP Semiconductors / Freescale
IC TUNER CABLE SILICON
40HVQFN




TDA8275AHN
NXP Semiconductors / Freescale
TDA8275AHN NXP




TDA8274AHN/C1+518
PHILIPS
TDA8274AHN/C1+518 PHILIPS




TDA8274AHN/C1,551
NXP Semiconductors / Freescale
IC TUNER CABLE SILICON
40HVQFN




TDA8274HN/C1
PHILIPS
TDA8274HN/C1 PHILIPS



TDA8274AHN/C1
PHILIPS
TDA8274AHN/C1 PHILIPS



TDA8275AC1
PHILIPS
TDA8275AC1 PHILIPS



TDA8274AHN/C1,557
NXP Semiconductors / Freescale
IC TUNER CABLE SILICON
40HVQFN

Hot Parts

More

- | | | | | |
|---------------------------|-------------------------|-----------------------|-----------------------|--------------------|
| ⚙️ AAT4280AIUV-3-T1 | ➡️ ACM1513-551-2PL-TLHF | ➡️ AD7523KNZ | D AP2302GN2 | ➡️ AP28G45GEO |
| ⚡️ ATFC-0402-1N5B-T | ⚙️ BCSM350-L | D BTA412Y-800B | ➡️ CTX20-1-52M-R | ➡️ DS1819BR-10+T&R |
| ⚙️ FAR-F6KA-1G9600-D4DQ-Z | ⚡️ FDP8030L | ⚙️ FT5202DE1 | ➡️ G12N60C3D | ➡️ INA322EA/2K5 |
| D IRFI9Z24GPBF | ⚙️ LD08CC473KAB1A | ⚡️ LMV931IDBVRG4 | ⚙️ LP5951MG-1.5 | ➡️ LT1077IS8#TRPBF |
| ➡️ LT3957EUHE#PBF | ➡️ LTC1598LCG#TRPBF | ⚙️ LTC2221IUP | ⚡️ LTC6101ACMS8#PBF | ➡️ LTM4614EV#PBF |
| ➡️ LTM8061EV-8.2#PBF | ➡️ MAX756CSA+T | D MAX8555EUB+ | ⚙️ MAZS0750ML+ | ⚡️ MBL400GS6NW |
| ⚙️ MDFS4N60D | D MIC5213-2.8BC5 | ➡️ MIG20J806HA | ➡️ MLG1608BR10JT000 | ➡️ MM74HCU04MTC |
| ⚡️ MT40A1G8WE-083E:B | ⚙️ PM50CLTA120 | ➡️ S-817A33APF-CUWTFG | ➡️ S-817B12AUA-CWBT2G | ➡️ SC431LISK-1TR |
| ⚙️ SM5S22-001HE3/2D | ⚡️ SPP8803TS8RGB | ⚙️ STB8N65M5 | D SW50DXC500 | ➡️ T1635-700G-TR |
| ➡️ TLV71310PDBVR | ⚙️ TLZ43-GS08 | ⚡️ TPS3803G15DCKRG4 | ⚙️ VSKD71/06P | ➡️ XC62FP3502PR |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited