









| | |
|---|--|
|  | <h2 style="color: red;">SP3223BEA</h2> |
| | <p>Manufacturer Part Number: SP3223BEA</p> <p>Manufacturer/Brand: SIPEX</p> <p>Part of Description: SIPEX SSOP20</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 7800 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation. See specs for product details.</p> | |

| Specifications | |
|----------------|---|
| Part Number | SP3223BEA |
| Manufacturer | SIPEX |
| Description | SIPEX SSOP20 |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 7800 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

SP3223BEA is New Original in Stock, Search SP3223BEA Datasheets, PDF, Inventory at Y-IC.com Online, Order SP3223BEA with warrantied and confidence. RFQ SP3223BEA : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|--|---|---|---|
|  SP3223EBCY SIPEX SP3223EBCY SIPEX |  SP3222HCY-L SIPEX SP3222HCY-L SIPEX |  SP3223EBCA-L/TR Exar Corporation IC TXRX RS232 INTELLIGENT 20SSOP |  SP3223EBCA SIPEX SP3223EBCA SIPEX |
|  SP3222EUEY-L/TR Exar Corporation IC TXRX RS232 ESD TRUE 20TSSOP |  SP3223EBCA-L Exar Corporation IC TXRX RS232 INTELLIGENT 20SSOP |  SP3223BCA SIPEX SIPEX SSOP20 |  SP3223BCY SIPEX SIPEX TSSOP20 |

Hot Parts More

- | | | | | |
|----------------------|-------------------------|-----------------------|-------------------|-------------------------|
| ⚙️ 12065E224MAT2A | ➡️ 170M3464 | ➡️ 7MBR25SA120-70 | D AP6N2K0EN-HF | ➡️ BCM5461SA11PFG |
| ⚡ C2012JB0J685M085AB | ⚙️ CAVC8T245QRHLRQ1 | D DS92CK16TMTCX | ➡️ FAN5608HMP | ➡️ FDS6681Z |
| ⚙️ FS6377-01G-XTP | ⚡ GJM0225C1E6R4DB01L | ⚙️ GRM188R72A331KA01J | ➡️ IRFPS43N50K | ➡️ IRFZ44EPBF |
| D IRKJ166-04 | ⚙️ IS61LPS12836A-200B2I | ⚡ LB1832V-TRM-E | ⚙️ LD025A3R3CAB2A | ➡️ LNBH26LPQR |
| ➡️ LP3966ESX-1.8 | ➡️ MB87841PF-G-BND | ⚙️ MC74VHC14DTR2G | ⚡ MCC25-18IO1 | ➡️ MD1501A23PNL |
| ➡️ MIC94355-GYMTTR | ➡️ NCP7240DPR2G | D NCP802SAN1T1 | ⚙️ PMBT3906VS | ⚡ QMK212SD121KD-T |
| ⚙️ RJK0601DPN | D S-75V00ANC | ➡️ S912XEQ512J3MALR | ➡️ SBE808-TL | ➡️ SIT8004AI-83-33E-125 |
| ⚡ SKKH15/12D | ⚙️ SMC3K75CA-M3/57 | ➡️ SMF9.1CA | ➡️ SN74F27N | ➡️ SPX385AM1-1.2/TR |
| ⚙️ SSL5235BTE | ⚡ STF701-T7 | ⚙️ TDZTR6.2 | D TE28F160C3BA90 | ➡️ TK6A55DA |
| ➡️ TL322IDR | ⚙️ TL431BIDBVR | ⚡ U642B-MY | ⚙️ XC6209B342MR | ➡️ ZXTN25012EFL |