

	<p>B39202B5140U410</p>
	<p>Manufacturer Part Number: B39202B5140U410</p> <p>Manufacturer/Brand: EPCOS</p> <p>Part of Description: EPCOS SMD</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 600 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	B39202B5140U410
Manufacturer	EPCOS
Description	EPCOS SMD
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	600 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

B39202B5140U410 is New Original in Stock, Search B39202B5140U410 Datasheets, PDF, Inventory at Y-IC.com Online, Order B39202B5140U410 with warrantied and confidence. RFQ B39202B5140U410 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>B39202B5310U410W3 Epcos / RF360 FILTER SAW RF</p>	 <p>B39202B4381P810 Epcos / RF360 FILTER SAW 1.8425/1.96GHZ 10SMD</p>	 <p>B39202B5146U410 Epcos / RF360 FILTER SAW RF</p>	 <p>B39202B5310U410 Epcos / RF360 FILTER SAW RF</p>
 <p>B39202B5064U410 Epcos / RF360 FILTER SAW RF 1950.0MHZ SMD</p>	 <p>B39202B5072U410W3 Epcos / RF360 FILTER SAW 2.01GHZ 6SMD</p>	 <p>B39202B7692A710 EPCOS B39202B7692A710 EPCOS</p>	 <p>B39202B5072U410 Epcos / RF360 FILTER SAW 2.01GHZ 6SMD</p>

Hot Parts

More

- | | | | | |
|--------------------|----------------------|------------------------|--------------------|-------------------|
| ⚙ 1775805-1 | ➡ ACH3218-102-TD01 | ➡ AD8021AR | D ADP3180JRUZ | ➡ AOZ1117TI-18L |
| ⊖ BD241BFP | ⚙ BXB50-48S12FHT | D CD40162BE | ➡ CD74ACT32M | ➡ FR05-S1-N-0-104 |
| ⚙ GBLCS03C | ⊖ GD10PJK120L2S | ⚙ GJM0335C1E6R9CB01D | ➡ GP1FA551 | ➡ H7N1005DSTL-E |
| D HT32F1655 | ⚙ ICS951462AGLF | ⊖ IMIFS781BZBT | ⚙ IPF04N03LGB | ➡ IR21824S |
| ➡ IRFS31N20DTRRPBF | ➡ ISL58831P | ⚙ LC75342M-TLM-E. | ⊖ LP3982ILD-1.8 | ➡ LTA015EEBFS8TL |
| ➡ LTC4352IDD#PBF | ➡ M306NNFHGP | D MAX4581EEE+T | ⚙ MAX8830EWE+T | ⊖ MC33375ST-2.5T3 |
| ⚙ MCR03EZJH152 | D MIC2168AYMM | ➡ NFM60R30T222T1M00-60 | ➡ OP284ESZ | ➡ P105CH06 |
| ⊖ PCA9542PW | ⚙ PI49FCT3807BQE+AMX | ➡ PM30-48S05 | ➡ PS2801C-1-F3 | ➡ R220CH08FK0 |
| ⚙ RB521-30 | ⊖ RT34063AGS | ⚙ SAFFB2G14FA0F0AR14 | D SUD08P06-155L-E3 | ➡ T491C335M035AT |
| ➡ TL061AMDT | ⚙ TLZ15C-GS08 | ⊖ TMP42C060P-5432 | ⚙ VI-J4M-MY | ➡ XBP1007-G |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited