

	<b>78M15/CJ78M15</b>	
	<b>Manufacturer Part Number:</b>	78M15/CJ78M15
<b>Manufacturer/Brand:</b>	Original	
<b>Part of Description:</b>	TO-252	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 32500 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications	
Part Number	78M15/CJ78M15
Manufacturer	Original
Description	TO-252
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	32500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

78M15/CJ78M15 is New Original in Stock, Search 78M15/CJ78M15 Datasheets, PDF, Inventory at Y-IC.com Online, Order 78M15/CJ78M15 with warrantied and confidence. RFQ 78M15/CJ78M15 : Info@Y-IC.com

You May Be Also Be interested

In:

 <b>78M20A</b> JRC JRC TO-220	 <b>78M12G</b> ON ON TO-252	 <b>78M15CDTG</b> ON ON D-PAK	 <b>78M12S</b> Grayhill, Inc. SWITCH SLIDE DIP SPST 150MA 30V
 <b>78M15</b> CJ CJ TO252	 <b>78M15CT</b> ON ON TO220-3	 <b>78M12CT</b> MOT 78M12CT MOT	 <b>78M12T</b> SANYO 78M12T SANYO

Hot Parts More

- |                      |                      |                      |                       |                         |
|----------------------|----------------------|----------------------|-----------------------|-------------------------|
| ⚙ 11-25844-02        | ➡ 1808CC222KAT9A     | ➡ 1808GA331KAT1AJ    | D 37211000001         | ➡ 5SDF13H4501           |
| ⚡ 7MBP50JA120-04     | ⚙ AAT1151IKS-3.3-T1  | D ADC10664CIWMX/NOPB | ➡ ALC105-GR           | ➡ AP4341SNTR-G1         |
| ⚙ AQY282SZ           | ⚡ AR1200-S85QEGQ     | ⚙ ASM1117-3.3        | ➡ ATMXT336T-MAUR      | ➡ BD4842G-TR            |
| D BD71817GW-E2       | ⚙ C2012JB1E155K085AC | ⚡ CL10B102KB85PNC    | ⚙ DCX143ZU-7-F        | ➡ EPM3032ATC44-7/I44-10 |
| ➡ F5KA833M0D4MGMZ    | ➡ FDMC86260          | ⚙ GRM1556P1H7R6DZ01D | ⚡ ISP1160BD/01        | ➡ LM4041CIM3-ADJTR      |
| ➡ LMV932MA/NOPB      | ➡ LNBTVS4-304S       | D LP3995ILDY-2.8     | ⚙ M21428G-11          | ⚡ MAF95029              |
| ⚙ MAX691ACPE         | D MC78L08A           | ➡ MIC4041DIM-1.2     | ➡ MIC5265-3.3YD5      | ➡ MRF24J40T-I/ML        |
| ⚡ MSM548332-30TS-K   | ⚙ MURS260-E3/52T     | ➡ NE25118-T1         | ➡ P280CH04            | ➡ PT6555-LQ             |
| ⚙ S-80925CNMC-Q8VT2S | ⚡ SC431CSK-5TR       | ⚙ SFT1446-TL-H       | D SGC6389Z            | ➡ SI-80512Z             |
| ➡ SI4682DY           | ⚙ SKD30/04AI         | ⚡ SMAJ440A           | ⚙ TSL1010-100M4R1-TPF | ➡ VI-810854             |