

	<h2 style="color: #E67E22;">ZL40203LDF1</h2>	
	Manufacturer Part Number:	ZL40203LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFFER 1:4 750MHZ 16QFN
	Datasheets:	1.ZL40203LDF1.pdf 2.ZL40203LDF1.pdf 3.ZL40203LDF1.pdf
Image may be representation. See specs for product details.	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
Shipment Way:		DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ZL40203LDF1
Manufacturer	Microsemi
Description	IC CLK BUFFER 1:4 750MHZ 16QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	750MHz
Package / Case	16-VFQFN Exposed Pad
Supplier Device Package	16-QFN (3x3)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	1:4
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40203LDF1 is New Original in Stock, Search ZL40203LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40203LDF1 Microsemi with warrantied and confidence. RFQ
ZL40203LDF1 : Info@Y-IC.com

You May Be Also Be interested

In:

 ZL40203LDG1 Microsemi IC CLK BUFFER 1:4 750MHZ 16QFN	 ZL40204LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN	 ZL40201LDF1 Microsemi IC CLK BUFFER 1:2 750MHZ 16QFN	 ZL40204LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN
 ZL40202LDF1 Microsemi IC CLK BUFFER 1:4 750MHZ 16QFN	 ZL40200LDG1 Microsemi IC CLK BUFFER 1:2 750MHZ 16QFN	 ZL40202LDG1 Microsemi IC CLK BUFFER 1:4 750MHZ 16QFN	 ZL40201LDG1 Microsemi IC CLK BUFFER 1:2 750MHZ 16QFN

Hot Parts

More

- | | | | | |
|-------------------|----------------------|----------------------|---------------------------|--------------------------|
| # 06035C162JAT2A | ↔ 182NQ030PBF | ⇒ AM80A-048L-050F4 | D AON7401L | ↔ AS1359-BTTT-26 |
| ↳ AT83C24B-Z1RUL | # BK1608LL271-T | D BL9193-33BAPRN | ⇒ BQ35100PWR | ↔ CC1210JKNP09BN332 |
| # CHL8214-02CRT. | ↳ D2223N400T11 | # DS90LV027AQMA | ↔ ELM92332A-S | ↔ EPM570F256C3N |
| D FJL43150TU | # GRM155C80J334KE01J | ↳ GRM1885C1H241JA01D | # HCPL-0708 | ↔ HG3-48RNG |
| ⇒ HSDL-3203-021 | ↔ L5991AD13TR | # LM1084RS-ADJ | ↳ LT1491AIDHC#PBF | ↔ MAX4004EUT |
| ↔ MAX4674EUE+T | ⇒ MAX700CSA+T | D MAX991ESA+ | # MB85RS256APNF-G-JNERE1. | ↳ MBM29SL800TD-12PFTN-ER |
| # MC10E112FN | D MCP1790-5002E/EB | ⇒ NT68652FG | ↔ PI6C2405A-1WEX | ↔ PM25CLS120 |
| ↳ PS7801E-1A-F3-A | # PSD112-16 | ↔ S-80925CNPF-G8VTFG | ⇒ ST200S04M | ↔ SY10E116JI |
| # SY89854UMG | ↳ T6100218BT | # TLC27L4MDR | D V300B5C200B | ↔ V375A2C160BL |
| ↔ VE-263-MY | # VI-J63-MX | ↳ W1524LC280 | # W25Q80DVZPIG | ↔ ZP400A1600V |

Contact us: **Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited