


 <b>ANALOG DEVICES</b> AHEAD OF WHAT'S POSSIBLE™	<b>ADV7526BCBZ-RL</b>
	<b>Manufacturer Part Number:</b> ADV7526BCBZ-RL
 Not Actual Photo YIC International Co., Limited.	<b>Manufacturer/Brand:</b> ADI (Analog Devices, Inc.)
	<b>Part of Description:</b> IC XMITTER HDMI/DVI 64-WLCSP
Image may be representation. See specs for product details.	<b>Datasheets:</b>  <a href="#">ADV7526BCBZ-RL.pdf</a>
	<b>RoHs Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, Stock Available.
	<b>Ship From:</b> Hong Kong
	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









### Specifications

Part Number	ADV7526BCBZ-RL
Manufacturer	ADI (Analog Devices, Inc.)
Description	IC XMITTER HDMI/DVI 64-WLCSP
Category	Integrated Circuits (ICs) > Linear - Video Processing
Part Status	Require For Quote & Check Stock
Series	-
Mounting Type	Surface Mount
Type	HDMI, DVI Transmitter
Applications	Recorders, Set-Top Boxes
Package / Case	64-WLCSP
Supplier Device Package	64-WLCSP
Packaging	Tape & Reel (TR)

ADV7526BCBZ-RL is New Original in Stock, Search ADV7526BCBZ-RL Datasheets, PDF, Inventory at Y-IC.com Online, Order ADV7526BCBZ-RL ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ ADV7526BCBZ-RL : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>ADV7535BCBZ-RL</b> ADI ADI WLCSP-49	 <b>ADV7525</b> AD ADV7525 AD	 <b>ADV7526BCBZ-RL</b> Anaren IC XMITTER HDMI/DVI 64-WLCSP	 <b>ADV7525BCBZ</b> ADI ADI BGA
 <b>ADV7525BCBZ-RL</b> ADI ADV7525BCBZ-RL ADI	 <b>ADV7533BCBZ-RL7</b> ADI (Analog Devices, Inc.) IC TXRX HDMI MIPI/DSI 49WLCSP	 <b>ADV7535BCBZ-RL7</b> ADI (Analog Devices, Inc.) IC TXRX HDMI MIPI/DSI 49WLCSP	 <b>ADV7524ABCBZ-P-1RL</b> ADI ADV7524ABCBZ-P-1RL ADI

### Hot Parts

More

- |                      |                         |                       |                    |                    |
|----------------------|-------------------------|-----------------------|--------------------|--------------------|
| ⊕ 08055A381FAT2A     | ↔ AK4103VF-X            | ⇒ AOD2910E            | D BQ27500DRZR-V120 | ⇒ BTS5231-2GS      |
| ⊖ BXA3-48D12-FSP     | ⊕ BZX585-C3V3/0603-3.3V | D C4532X7R2A225K230KA | ⇒ CXA3525R-T4      | ⇒ DR1040-820-R     |
| ⊕ GCM2165C1H202JA16D | ⊖ GJ831CR61E106KE83L    | ⊕ GRB12150D-3W-A      | ↔ H11A5100SR2M     | ⇒ ICE65L04F-LCS63C |
| D INA202AIDGKR       | ⊕ IRF520NSTR            | ⊖ IRLI540GPBF         | ⊕ ISL21009DFB850Z  | ⇒ LM431CCMX        |
| ⇒ LQW31HN84NJ03L     | ↔ LT1302CS8-5           | ⊕ LTC1540IS8#PBF      | ⊖ M74HC299B1       | ⇒ MAX16946GTE/V+T  |
| ↔ MAX810MD           | ⇒ MAX8559ETAM1+T        | D MC81F4104M          | ⊕ MG50M2CK2        | ⊖ MG600Q1U551      |
| ⊕ MT88E43BS          | D NJM2888F31            | ⇒ P4SMAJ20CA          | ↔ PI90LV031ALX     | ⇒ RS1E320GN        |
| ⊖ S3282LCF0B         | ⊕ SA85CA-E3/73          | ↔ SC2614IMLTR         | ⇒ SKKT41/14EL1     | ⇒ SKM150GAL121D    |
| ⊕ SMBJ12AT3G         | ⊖ SMBT1018LT1           | ⊕ SMBT1071            | D SMDT-70I-22      | ⇒ TISP4265M3AJR-S  |
| ↔ TLV2252AQDRQ1      | ⊕ TMP100NA/3KG4         | ⊖ TPD1E10B09DPYT      | ⊕ VL53L0CBV0DH/1   | ⇒ VS-40CPQ080PBF   |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited