

	<h2 style="color: red;">TC33X-2-103G</h2>
	<p>Manufacturer Part Number: TC33X-2-103G</p> <p>Manufacturer/Brand: BOURNS</p> <p>Part of Description: BOURNS 3x3</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 5500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	TC33X-2-103G
Manufacturer	BOURNS
Description	BOURNS 3x3
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	5500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

TC33X-2-103G is New Original in Stock, Search TC33X-2-103G Datasheets, PDF, Inventory at Y-IC.com Online, Order TC33X-2-103G with warrantied and confidence. RFQ TC33X-2-103G : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>TC33X-2-104E Bourns, Inc. TRIMMER 100K OHM 0.1W J LEAD TOP</p>	 <p>TC33X-2-104G Bourns, Inc. TRIMMER 100K OHM 0.1W J LEAD TOP</p>	 <p>TC33X-2-105E Bourns, Inc. TRIMMER 1M OHM 0.1W J LEAD TOP</p>	 <p>TC33X-2-103E Bourns, Inc. TRIMMER 10K OHM 0.1W J LEAD TOP</p>
 <p>TC33X-2-102E Bourns, Inc. TRIMMER 1K OHM 0.1W J LEAD TOP</p>	 <p>TC33X-2-102G Bourns, Inc. TRIMMER 1K OHM 0.1W J LEAD TOP</p>	 <p>TC33X-2-103E BOURNS BOURNS SMD</p>	 <p>TC33X-2-103G Bourns, Inc. TRIMMER 10K OHM 0.1W J LEAD TOP</p>

Hot Parts

[More](#)

- | | | | | |
|---------------------------|----------------------|---------------------|-----------------------|------------------------|
| ⚙️ 12061A161JAT2A | ⚙️ 18121C224KAZ2A | ➡️ 6DI20S-050C | D BA78M20FP-E2 | ➡️ BD68888EKV-E2 |
| ⚙️ BLF6G10-135RN | ⚙️ BQ24026DRCR | D BYM12-600 | ➡️ BZT52-C2V4-R1 | ➡️ C5750C0G3A103J280KC |
| ⚙️ CL02A104KQ2NNNC | ⚙️ CN160-15-110 | ⚙️ CY7C65211-24LTXI | ⚙️ DPX255875DT-0016B1 | ➡️ DZ2S068COL |
| D EM6353BZ2SP3B-4.4+ | ⚙️ FDMF6820C | ⚙️ FIN1104MTC | ⚙️ G6JU-2FL-Y-5V | ➡️ GCM188R71H224KA64D |
| ➡️ GRM2196T2A6R1DD01D | ⚙️ HPFC-6700C | ⚙️ HV5623K7-G | ⚙️ IRFS4620 | ➡️ ISL9211AIRU58XZ |
| ⚙️ ISP1763AETTM | ➡️ K9F5608UOD-PCBO | D KSA1175-G | ⚙️ LM2766M6X/NOPB | ⚙️ MAX876ACSA |
| ⚙️ MB85RS128APNF-G-JNERE1 | D MB86295SPB-GS-JXE1 | ➡️ MBR1635CT | ⚙️ MX29GL256FHXGI-90Q | ➡️ NAU8822AYG |
| ⚙️ NTD40N03RT4 | ⚙️ NTD6414ANT4G | ⚙️ PIC16LF818-I/ML | ➡️ SC112CSK-3.8.TR | ➡️ SN65EL16DR |
| ⚙️ SN74LVCU04ADBR | ⚙️ STS6218CLC | ⚙️ TC1015-2.6VCT | D TC7SET126F | ➡️ TFM201610A-2R2M-T00 |
| ⚙️ TPS61200DRCR | ⚙️ VS-10MQ100NPBF | ⚙️ VS-45L10 | ⚙️ VT239WFQX-ADJ | ➡️ X9241AWSIZ |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited