


	DS4160P+
	Manufacturer Part Number: DS4160P+
	Manufacturer/Brand: Maxim Integrated
	Part of Description: IC OSC CLOCK 160MHZ 10-LCCC
	Datasheets:  DS4160P+.pdf
	RoHS Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	DS4160P+
Manufacturer	Maxim Integrated
Description	IC OSC CLOCK 160MHZ 10-LCCC
Category	Integrated Circuits (ICs) > Clock/Timing - Programmable
Part Status	Require For Quote & Check Stock
Series	DS4-XO
Frequency	160MHz
Current - Supply	74mA
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Clock Oscillator
Package / Case	10-LCCC Exposed Pad
Supplier Device Package	10-LCCC (5x3.2)
Voltage - Supply	3.135 V ~ 3.465 V
Count	-
Packaging	Tube

DS4160P+ is New Original in Stock, Search DS4160P+ Datasheets, PDF, Inventory at Y-IC.com Online, Order DS4160P+ Maxim Integrated with warrantied and confidence. RFQ DS4160P+ : Info@Y-IC.com

You May Be Also Be interested

In:

 DS4156D+ Maxim Integrated IC OSC CLOCK 156.25MHZ 10-LCCC	 DS4212BN+ Maxim Integrated IC OSC CLOCK 212.5MHZ 10-LCCC	 DS4206-GCN DALLAS DALLAS SOP16	 DS4201 DALLAS DALLAS DIP
 DS4156PW+ Maxim Integrated IC OSC CLOCK 156.25MHZ 10LCCC	 DS4212AN+ Maxim Integrated IC OSC CLOCK 212.5MHZ 10-LCCC	 DS4160D+ Maxim Integrated IC OSC CLOCK 160MHZ 10-LCCC	 DS4155P+ Maxim Integrated IC OSC CLOCK 155.52MHZ 10-LCCC

Hot Parts

More

- | | | | | |
|--------------------|-------------------|------------------------|-----------------------|----------------------------|
| ⊛ 0402YA331KAT2A | ↔ 08053C822KAT2A | ⇒ 1206ZC225MAT2A | D 161RDF80 | ⇒ 2SP0325S2A0-CM1800DY-34S |
| ⊣ 6MBI200XXA120-50 | ⊛ A3980KLP | D ACPL-217-50CE | ⇒ ADM823TYRJZ-R7 | ⇒ ADS1294RIZXGR |
| ⊛ AK8452VN-L | ⊣ AP1115BY25L-13 | ⊛ AT87F51-33AC | ↔ BWR-15/100-D48 | ⇒ C3216JB2E683M160AA |
| D CAT93C66J-26490 | ⊛ CDBB140-G | ⊣ CGA3E2NP02A270J080AA | ⊛ CGB3B1JB1A475K055AC | ⇒ CL21B472KC6WPNC |
| ⇒ CM3018-29ST | ↔ DMTH4004SPS | ⊛ FS20R06KFS | ⊣ GRM1886R1H3R8CZ01D | ⇒ GRM219F51H154ZA01D |
| ↔ HMK325B7225KN-T | ⇒ ISL9001IRNZ-T | D LI0603G221R-10 | ⊛ LL1608-FH68NJ | ⊣ MC10ELT25DR |
| ⊛ MCT5211TVM | D MIC2287-34YML | ⇒ PI2EQX3201BLZFE | ↔ R5F1027AAA00NA#U0 | ⇒ S8550LT12TY |
| ⊣ SDM2F100G04FE | ⊛ SKKT92/16D | ↔ SM1105NSK | ⇒ STP6NK60ZFP | ⇒ TLC393CPSR |
| ⊛ TLV2464AIPWR | ⊣ TMK063CH080CP-F | ⊛ TPS77633QPWREP | D UNR51A5G0LS0+ | ⇒ V48A24C500B |
| ↔ VI-231-03 | ⊛ VI-26V-CW | ⊣ VLS3010ET-220M | ⊛ VLZ5V1B-GS08 | ⇒ WG5035S |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited