


	<b>R5F10RF8AFP#V0</b>
	<b>Manufacturer Part Number:</b> R5F10RF8AFP#V0
	<b>Manufacturer/Brand:</b> Renesas Electronics America
	<b>Part of Description:</b> IC MCU 16BIT 8KB FLASH 44LQFP
<b>Datasheets:</b>	 <a href="#">R5F10RF8AFP#V0.pdf</a>
<b>RoHS Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	R5F10RF8AFP#V0
Manufacturer	Renesas Electronics America
Description	IC MCU 16BIT 8KB FLASH 44LQFP
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	RL78/L12
Operating Temperature	-40°C ~ 85°C (TA)
Package / Case	44-LQFP
Supplier Device Package	44-LQFP (10x10)
Peripherals	DMA, LCD, LVD, POR, PWM, WDT
Core Processor	RL78
Speed	24MHz
Number of I/O	29
EEPROM Size	2K x 8
RAM Size	1K x 8
Core Size	16-Bit
Connectivity	CSI, I <sup>2</sup> C, LIN, UART/USART
Program Memory Size	8KB (8K x 8)
Program Memory Type	FLASH
Voltage - Supply (Vcc/Vdd)	1.6 V ~ 5.5 V
Data Converters	A/D 7x8/10b
Oscillator Type	Internal
Packaging	Tray

R5F10RF8AFP#V0 is New Original in Stock, Search R5F10RF8AFP#V0 Datasheets, PDF, Inventory at Y-IC.com Online, Order R5F10RF8AFP#V0 Renesas Electronics America with warranted and confidence. RFQ R5F10RF8AFP#V0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>R5F10RBCAFP#X0</b> Renesas Electronics America IC MCU 16BIT 32KB FLASH 32LQFP</p>	 <p><b>R5F10RBCGFP#50</b> Renesas Electronics America IC MCU 16BIT 32KB FLASH 32LQFP</p>	 <p><b>R5F10RFAGFP#V0</b> Renesas Electronics America RL78/L12 16K/1K+2K 44QFP - 40_+85</p>	 <p><b>R5F10RBCGFP#V0</b> Renesas Electronics America IC MCU 16BIT 32KB FLASH 32LQFP</p>
 <p><b>R5F10RBCGFP#30</b> Renesas Electronics America IC MCU 16BIT 32KB FLASH 32LQFP</p>	 <p><b>R5F10RFAGFP#X0</b> Renesas Electronics America RL78/L12 16K/1K+2K 44QFP - 40_+85</p>	 <p><b>R5F10RFAAFP#V0</b> Renesas Electronics America IC MCU 16BIT 16KB FLASH 44LQFP</p>	 <p><b>R5F10RF8AFP#X0</b> Renesas Electronics America IC MCU 16BIT 8KB FLASH 44LQFP</p>

Hot Parts

More

- |                        |                    |                   |                       |                      |
|------------------------|--------------------|-------------------|-----------------------|----------------------|
| ⊛ 04025A2R7DAT4A       | ↔ 06031A7R5BAT2A   | ⇒ 0805YC824KAT2A  | D A618S06TDC          | ⇒ AD706ARZ-REEL      |
| ⊣ AP2127K-3.3TRG1      | ⊛ APL5312-12BI-TRL | D BF1208+115      | ⇒ C3216X5R1E335M160AA | ⇒ C3225X7R1H105K/1.6 |
| ⊛ CKG57NX7R1H226MT0S9W | ⊣ DBS150A15        | ⊛ ELM9721NAA-S    | ↔ F931C105MAA         | ⇒ FDD26AN06          |
| D FDS86242             | ⊛ FPD87314BBSAVJD  | ⊣ FSA2147K8X      | ⊛ GJM0225C1E9R4CB01L  | ⇒ GRM1556P1H9R0D201D |
| ⇒ H11D4.3S             | ↔ HI2220P271R-10   | ⊛ HIP6603BCB      | ⊣ IMD10AT108          | ⇒ IRF630NSTRLPBF     |
| ↔ IRFHS8342TR2PBF      | ⇒ ISL24837AIRZ-T13 | D ITR20001/T      | ⊛ LD1117AL-33-AA3-A-R | ⊣ LM79L12ACMX        |
| ⊛ LMBD301LT1G          | D LP3962EMP-1.8    | ⇒ LT5516EUF#TRPBF | ↔ LTC4069EDC#PBF      | ⇒ MC145483SD         |
| ⊣ MCT2ETVM             | ⊛ MMK60A160B       | ↔ PH100S48-5      | ⇒ PS1R5-0512          | ⇒ PS2761-1L-F4-A     |
| ⊛ RT0603BRD075K6       | ⊣ SC1104AIS.TR     | ⊛ SMP1304-005     | D SN74LS32DR          | ⇒ SP103358CFA        |
| ↔ SRF20200C            | ⊛ TL594CNSRG4      | ⊣ TPS73633DBVRG4  | ⊛ TPSMA16HE3/61T      | ⇒ XC6221A332MRN      |