


	<b>74HC4538PW,118</b>
	<b>Manufacturer Part Number:</b> 74HC4538PW,118
	<b>Manufacturer/Brand:</b> Nexperia
	<b>Part of Description:</b> IC MULTIBIBRTR DUAL MONO 16TSSOP
<b>Datasheets:</b>	 <a href="#">74HC4538PW,118.pdf</a>
<b>RoHs Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	74HC4538PW,118
Manufacturer	Nexperia
Description	IC MULTIBIBRTR DUAL MONO 16TSSOP
Category	Integrated Circuits (ICs) > Logic - Multivibrators
Part Status	Require For Quote & Check Stock
Series	74HC
Operating Temperature	-40°C ~ 125°C
Mounting Type	Surface Mount
Package / Case	16-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	16-TSSOP
Voltage - Supply	2 V ~ 6 V
Logic Type	Monostable
Current - Output High, Low	5.2mA, 5.2mA
Schmitt Trigger Input	No
Independent Circuits	2
Propagation Delay	25ns
Packaging	Tape & Reel (TR)

74HC4538PW,118 is New Original in Stock, Search 74HC4538PW,118 Datasheets, PDF, Inventory at Y-IC.com Online, Order 74HC4538PW,118 Nexperia with warrantied and confidence.  
RFQ 74HC4538PW,118 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>74HC4538PW</b> NXP 74HC4538PW NXP</p>	 <p><b>74HC4538PW,112</b> Nexperia IC MULTIVIBRTR DUAL MONO 16TSSOP</p>	 <p><b>74HC4538PW-118</b> PHILIPS 74HC4538PW-118 PHILIPS</p>	 <p><b>74HC4543B1</b> ST 74HC4543B1 ST</p>
 <p><b>74HC4538N</b> PHILIPS 74HC4538N PHILIPS</p>	 <p><b>74HC4538PW-Q100,11</b> Nexperia IC MULTIVIBRATOR MONO 16TSSOP</p>	 <p><b>74HC4543D</b> PHI PHI SOP</p>	 <p><b>74HC4538P</b> HIT HIT DIP16</p>

Hot Parts

More

- |                    |                      |                 |                    |                    |
|--------------------|----------------------|-----------------|--------------------|--------------------|
| 08055A330JAQ2A     | BAR64-04             | BLM18KG331SN1D  | BSZ050N03LSG       | BZX584C22-7-F      |
| CAT5121TPI-10-T    | CGA6P1X7S0J476M250AC | CPDQR5V0-HF     | DS75U+TR           | DS9638CM           |
| DT251N04KOF        | FMMT560QTA           | FOD3182S        | GRM1555C1H1R6BA01D | GRM1555C1H9R6DZ01D |
| GRM1555C2A3R2CA01J | GRM2197U2A9R3DD01D   | HMC1118LP3DETR  | ICS9DB801BGLFT     | IKD04N60RF         |
| ISL6614IRZ-T       | KSC5039FTU           | LMS1587ACS-1.5  | LMX393AUA+         | LPC2458FET180      |
| LT1117IST-5.0      | LT1460EIS8-2.5       | MAX394EWP       | MB90097PFV-G-105   | MDP15N60GTH        |
| MFC55TA120         | MT29F4G16AACWC:C     | NCP5612MUTBG    | PAM2421AECADJR     | PBRC4.00GR50Y000   |
| RJK0330DPB-01      | RWT4812.5-5.4C       | SI4160DY-T1-GE3 | SKR135F10          | SP7121EK-L         |
| SS1FL3HM3/H        | STS3DNF30L           | TDA6500TT/C4    | TS831-3I           | UNR521NJ01FX       |
| UPM2015BN          | VI-274-IW            | VI-710024       | VU36-18N08         | ZP7000A1400V       |