


	<h2 style="color: #e67e22;">15330R-2500</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">15330R-2500</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Echelon</a>
	<b>Part of Description:</b>	IC TXRX POWER LINE 38TSSOP
<b>Datasheets:</b>	 <a href="#">15330R-2500.pdf</a>	
<b>RoHs Status:</b>	 Lead free / RoHS	
<b>Stock Condition:</b>	Compliant New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	









### Specifications

Part Number	15330R-2500
Manufacturer	Echelon
Description	IC TXRX POWER LINE 38TSSOP
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	PL3170®
Operating Temperature	-40°C ~ 85°C
Mounting Type	Stud, 7/16" (M10)
Interface	SPI, UART
Applications	Smart Transceiver
Package / Case	38-TFSOP (0.173", 4.40mm Width)
Supplier Device Package	38-TSSOP
Voltage - Supply	4.75 ~ 5.25 V
Core Processor	Neuron
Number of I/O	12
RAM Size	2K x 8
Program Memory Type	EEPROM (4 kB)
Controller Series	-
Packaging	Tape & Reel (TR)

15330R-2500 is New Original in Stock, Search 15330R-2500 Datasheets, PDF, Inventory at Y-IC.com Online, Order 15330R-2500 Echelon with warrantied and confidence. RFQ 15330R-2500 : Info@Y-IC.com

### You May Be Also Be interested

In:

  <b>1533123</b> Phoenix Contact CABLE 4POS	  <b>1533107</b> Phoenix Contact CABLE 4POS	  <b>1533068</b> Phoenix Contact CABLE	  <b>1533042</b> Phoenix Contact CABLE 5POS
  <b>15330R-5</b> Echelon IC SOC TXRX 38TSSOP 1=1 PIECE	  <b>1533110</b> Phoenix Contact CABLE 4POS	  <b>15330R-1000</b> Echelon IC TXRX POWER LINE 38TSSOP	  <b>1533071</b> Phoenix Contact CABLE

### Hot Parts More

- |                    |                    |                   |                   |                    |
|--------------------|--------------------|-------------------|-------------------|--------------------|
| 08051A271K4T2A     | 1812SC222KATME     | 2DI50Z-100(A)     | AAT1106ICB-1.8-T1 | ADV7480WBBCZ-RL    |
| AOT20B60D          | AR3004S20          | ATMEGA48PA-15MZ   | BC857BFE6327      | BD2232G-GTR        |
| BF1005SL6760       | BMR6114325         | C2012X7R2A223M/10 | CB1-M-24V         | CL32B223KGFNNWE    |
| CNY17F-2           | DS1706SESA+        | EMA1001-50SA08GRR | F1300NC45P        | GCM1885C1H3R9CA16D |
| GRM033R71C103KE14D | GRM1886R1H6R8DZ01D | HIP1011CBZA       | IRFS4510TRLPBF    | ISL6217ACVZ-T      |
| ISP1761ET          | LD051C102JAB2A     | LT1499IS          | LTC1149CG#TR      | LTC4305CGN#TRPBF   |
| MC74ACT157DR2      | MCD312-08IO8       | MIC2545A-1YMTR    | N330CH22KOO       | NB637EL-LF-Z       |
| NLC453232T-121K-PF | PCF50603HN/05/N03  | PI5C3390QEX       | PTH04040WAD       | R1EX24128ASAS0A    |
| S-1170B31PD-0TQTFG | SBT150-10Y-DL-E    | ST1S09PUR         | STB85NF3LL        | STF8NM60ND         |
| TA48M018F          | TMK063CG220JP-F    | TPS63036YFGT      | V18MLA0603NH      | VBO105-14N07       |