
















| | |
|---|--|
|  | ZL40219LDF1 |
| | Manufacturer Part Number: ZL40219LDF1 |
|  | Manufacturer/Brand: Microsemi |
| | Part of Description: IC CLK BUFFER 1:8 750MHZ 32QFN |
| | Datasheets: <ul style="list-style-type: none">  1.ZL40219LDF1.pdf  2.ZL40219LDF1.pdf  3.ZL40219LDF1.pdf |
| | RoHs Status:  Lead free / RoHS |
| | Stock Condition:  New original, Stock Available. |
| | Ship From: Hong Kong |
| Image may be representation. See specs for product details. | Shipment Way: DHL/Fedex/TNT/UPS/EMS |

Specifications

| | |
|-----------------------------|--|
| Part Number | ZL40219LDF1 |
| Manufacturer | Microsemi |
| Description | IC CLK BUFFER 1:8 750MHZ 32QFN |
| Category | Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C |
| Mounting Type | Surface Mount |
| Type | Fanout Buffer (Distribution) |
| Frequency - Max | 750MHz |
| Package / Case | 32-VFQFN Exposed Pad |
| Supplier Device Package | 32-QFN (5x5) |
| Number of Circuits | 1 |
| Voltage - Supply | 2.375 V ~ 3.465 V |
| Output | LVDS |
| Input | CML, HCSL, LVCMOS, LVDS, LVPECL |
| Ratio - Input:Output | 1:8 |
| Differential - Input:Output | Yes/Yes |
| Packaging | Tape & Reel (TR) |

ZL40219LDF1 is New Original in Stock, Search ZL40219LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40219LDF1 Microsemi with warrantied and confidence. RFQ
ZL40219LDF1 : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|---|
| In:  ZL40220LDG1 Microsemi IC CLK BUFFER 2:6 750MHZ 32QFN |  ZL40218LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN |  ZL40217LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN |  ZL40216LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN |
|  ZL40221LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN |  ZL40217LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN |  ZL40218LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN |  ZL40221LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN |

Hot Parts

[More](#)

- # 0805ZC683KAT2A
- ↔ 12105C394JAT2A
- ⇒ 25LC320-I/SN
- D 70MT100KB
- ↔ ADP3110KR2-RL
- # ADR5044AKSZ-REEL7
- D AM-RT4-433
- ↔ AS3406-12
- # AT25DF041A-SSH
- ↔ BS62LV256PIP-70
- # BSC050N03NS3G
- ↔ C1005CH2A331J050BA
- D CBT3245ABQ
- # CD4515BCN
- ↔ CDZFHT2RA5.1B
- # CGA3E3X5R1H154K080AB
- ↔ CY2304SXC-1T
- ⇒ DDZ12B-7
- ↔ GRM0335C2A9R9DA01D
- # GRM155R61E683MA87D
- ↔ GRM1885C1H8R9DA01D
- ↔ HUFA76407DK8T
- ↔ HUL6278S11AU
- ⇒ HZD150-110S48
- D IPD60R800CE
- # JMK212ABJ475MGHT
- ↔ LDB212G4020C-001
- # LM2574M-3.3
- D LT3693EMSE#PBF
- ⇒ LTC3204BEDC-3.3#TRPBF
- ↔ LTC6802IG-1#TRPBF
- ↔ LXA06T600
- ↔ MDV1527URH
- # NJU7241F25
- ↔ NM93C86AM8
- ⇒ PVU414S-T
- ↔ RS8511BXF
- # SD253N16S1MSV
- ↔ SKKD500-12
- # SKMT92/16E
- D TAJC226M016RNJ
- ↔ TCSCS0J476MBCAR
- ↔ TPS74301KTWT
- ↔ TPS74701DRCRG4
- # VI-BW0-EW
- ↔ TCSCS0J476MBCAR
- ↔ WG20021SP

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited