

	SY100E155JC
	Manufacturer Part Number: SY100E155JC
	Manufacturer/Brand: Micrel / Microchip Technology
	Part of Description: IC MUX-LATCH 6-BIT 2:1 28-PLCC
Datasheets:  SY100E155JC.pdf	RoHs Status: Contains lead / RoHS non-compliant
Stock Condition: New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	SY100E155JC
Manufacturer	Micrel / Microchip Technology
Description	IC MUX-LATCH 6-BIT 2:1 28-PLCC
Category	Integrated Circuits (ICs) > Logic - Signal Switches,
Part Status	Require For Quote & Check Stock
Series	100E
Operating Temperature	0°C ~ 85°C
Mounting Type	Surface Mount
Type	Multiplexer
Package / Case	28-LCC (J-Lead)
Supplier Device Package	28-PLCC (11.5x11.5)
Voltage - Supply	-4.2 V ~ -5.5 V
Circuit	6 x 2:1
Voltage Supply Source	Single Supply
Current - Output High, Low	-
Independent Circuits	1
Packaging	Tube

SY100E155JC is New Original in Stock, Search SY100E155JC Datasheets, PDF, Inventory at Y-IC.com Online, Order SY100E155JC Micrel / Microchip Technology with warrantied and confidence. RFQ SY100E155JC : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SY100E151JZ Micrel / Microchip Technology IC D-TYPE POS TRG SNGL 28PLCC</p>	 <p>SY100E154JZ TR Micrel / Microchip Technology IC MUX-LATCH 5BIT 2:1 28PLCC</p>	 <p>SY100E151JZ TR Micrel / Microchip Technology IC D-TYPE POS TRG SNGL 28PLCC</p>	 <p>SY100E154JC Micrel / Microchip Technology IC MUX-LATCH 5-BIT 2:1 28- PLCC</p>
 <p>SY100E156JC Micrel / Microchip Technology IC MUX-LATCH 3-BIT 4:1 28- PLCC</p>	 <p>SY100E155JZ Micrel / Microchip Technology IC MUX-LATCH 6BIT 2:1 28-PLCC</p>	 <p>SY100E154JZ Micrel / Microchip Technology IC MUX-LATCH 5BIT 2:1 28-PLCC</p>	 <p>SY100E156JZ Micrel / Microchip Technology IC MUX-LATCH 3BIT 4:1 28-PLCC</p>

Hot Parts

[More](#)

- | | | | | |
|-------------------|---------------------|--------------------|-----------------------------|-----------------|
| 0201ZC103KAT2A | 0805YC683KAT2A | 12065A621FAT2A | D 5962-00A1701NXB/11624-001 | 7MBR50SA060-70 |
| A05D15/150Z | ACM2012-121-2P-T000 | AD1981HDJSTZ | ADS7864Y/250 | AOTF9N90A |
| ASL-3W-K | B39431-B4029-Z810 | BL919815BAPRN | BYT54J-TAP | C055-02B |
| CDRH73-331MC | CSCA100A00B15B01 | CY8CTMA340-FNI-09T | DS90C383MTDX/NOPB | EP3C16F256I7N |
| ICL7660ACBA | ICS650R-22T | ISL6522CB-T | ISL9491AERZ | LBN150B01-7 |
| LDK120C18R | LTC3545EUD#PBF | M38027M8-526FP | MAX3232CWE+T | MC14050B |
| MC35XS3400DPNA | MCD94-06io8B | ML6428CS1-NL | MTP20N06 | PSB21525HV2.1GD |
| PSKD142/18 | RF071LAM4S | RF1694TR13-5K | RF5125TR7 | RT9193-39PBG |
| SMBJ43A-E3 | SP312EET | TAJY336K020RNJ | THS4275DRG4 | TJA1021T/20/C |
| TMS320LBC53SPZ-80 | TSB41LV03PPF | V24C12T50BN | VI-BNO-02 | W4096ZC450 |