
	R5F10MPEDFB#30
	Manufacturer Part Number: R5F10MPEDFB#30 Manufacturer/Brand: Renesas Electronics America Part of Description: IC MCU 16BIT 64KB FLASH 100LQFP RoHS Status:  Lead free / RoHS Stock Condition: ^{Compliant} New original, Stock Available. Ship From: Hong Kong Shipment Way: DHL/Fedex/TNT/UPS/EMS
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	R5F10MPEDFB#30
Manufacturer	Renesas Electronics America
Description	IC MCU 16BIT 64KB FLASH 100LQFP
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	RL78/I1B
Operating Temperature	-40°C ~ 85°C (TA)
Peripherals	Brown-out Detect/Reset, LCD, LVD, POR, PWM, WDT
Core Processor	RL78
Speed	24MHz
Number of I/O	69
EEPROM Size	-
RAM Size	6K x 8
Core Size	16-Bit
Connectivity	CSI, I ² C, IrDA, LIN, UART/USART
Program Memory Size	64KB (64K x 8)
Program Memory Type	FLASH
Voltage - Supply (Vcc/Vdd)	1.9 V ~ 5.5 V
Data Converters	A/D 6x10b, 4x24b
Oscillator Type	Internal

R5F10MPEDFB#30 is New Original in Stock, Search R5F10MPEDFB#30 Datasheets, PDF, Inventory at Y-IC.com Online, Order R5F10MPEDFB#30 Renesas Electronics America with warrantied and confidence. RFQ R5F10MPEDFB#30 : Info@Y-IC.com

You May Be Also Be interested

In:

 R5F10MPGDFOB#30 Renesas Electronics America IC MCU 16BIT 128KB FLASH 100QFP	 R5F10MMGDFOB#50 Renesas Electronics America IC MCU 16BIT 128KB FLASH 80LQFP	 R5F10KGCANA#U0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 48HWQFN	 R5F10MPEDFB#50 Renesas Electronics America IC MCU 16BIT 64KB FLASH 100LQFP
 R5F10MMEDFB#50 Renesas Electronics America IC MCU 16BIT 64KB FLASH 80QFP	 R5F10MPGDFOB#50 Renesas Electronics America IC MCU 16BIT 128KB FLASH 100QFP	 R5F10MMEDFB#30 Renesas Electronics America IC MCU 16BIT 64KB FLASH 80QFP	 R5F10MMGDFOB#30 Renesas Electronics America IC MCU 16BIT 128KB FLASH 80LQFP

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|-------------------------|--------------------|
| ⊕ 02013A9R1BAT2A | ↔ 12062C152KAT4A | ⇒ 2MBI600VE-120-50 | D ACM4532-801-2P-T | ⇒ AD8022ARZ-REEL7 |
| ⊖ AOZ1282CI | ⊕ BA25BCOFP-2E | D BZG03C18 | ⇒ C2012X5R1A475KT00HE | ⇒ DD130A-20 |
| ⊕ DEA165375BT-2100B1 | ⊖ EL5421CYZ | ⊕ ELM7SH00MBEL | ↔ FAN53555UC09X | ⇒ FDS6990A_NL |
| D GCM1555C1H150FA16D | ⊕ GRM0225C1E5R3CA03L | ⊖ GRM188R60J334KA01D | ⊕ HUFA76429D3ST | ⇒ KSC1623-Y-MTF |
| ⇒ KSH32CTF-NL | ↔ LCB31B2450D1 | ⊕ LD061C682JAB2A | ⊖ LM1117MP-ADJ | ⇒ LT1934IS6 |
| ↔ LT8611EUDD#TRPBF | ⇒ LTC1044CN8#PBF | D LTV-816S-TA1-C | ⊕ MAS110S12R-022 | ⊖ MAX453CPA |
| ⊕ PH100F24-3/MOT | D PKC4113PI | ⇒ PVZ3K472C01R02 | ↔ RF2365TR7 | ⇒ RT9014A-CSPQW |
| ⊖ RT9161-15CX | ⊕ S25FL004A0LMFI001 | ↔ SDFL1608S5N6ST | ⇒ SF100AA50 | ⇒ SFR9210TF |
| ⊕ SK310B-R/AD | ⊖ SN74HC573AQDWRQ1 | ⊕ SUP90N08-06 | D TCSCS1A226MBAR-10V22U | ⇒ THGBMHG7C2LBAWR |
| ↔ TPC8003-H | ⊕ TPS61180RTERG4 | ⊖ VLF302512MT-2R2M | ⊕ VS-20L15TSPBF | ⇒ XC7Z010-1CLG400I |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited