



	<h2 style="color: red;">RX-8035LC:B0</h2>	
	<b>Manufacturer Part Number:</b>	RX-8035LC:B0
	<b>Manufacturer/Brand:</b>	Epson
	<b>Part of Description:</b>	IC RTC EVENT REC I2C 12-VSOJ
<b>Datasheets:</b>	<a href="#">  1.RX-8035LC:B0.pdf                 </a> <a href="#">  2.RX-8035LC:B0.pdf                 </a>	
<b>RoHs Status:</b>	 Lead free / RoHS	
<b>Stock Condition:</b>	Compliant New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	

Specifications	
Part Number	RX-8035LC:B0
Manufacturer	Epson
Description	IC RTC EVENT REC I2C 12-VSOJ
Category	Integrated Circuits (ICs) > Clock/Timing - Real Time
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Time Event Recorder
Features	Alarm
Interface	I <sup>2</sup> C, 2-Wire Serial
Package / Case	12-TFSOJ (0.094", 2.40mm Width)
Supplier Device Package	12-VSOJ
Voltage - Supply	2.4 V ~ 5.5 V
Memory Size	-
Time Format	HH:MM:SS (12/24 hr)
Date Format	YY-MM-DD-dd
Voltage - Supply, Battery	1 V ~ 5.5 V
Current - Timekeeping (Max)	2.5µA @ 3V
Packaging	Tape & Reel (TR)

RX-8035LC:B0 is New Original in Stock, Search RX-8035LC:B0 Datasheets, PDF, Inventory at Y-IC.com Online, Order RX-8035LC:B0 Epson with warrantied and confidence. RFQ RX-8035LC:B0 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p><b>RX-8035SA:AA0:PURE SN</b> Epson IC RTC EVENT REC I2C 14-SOP</p>	 <p><b>RX-8035LC:AC0 PURE SN</b> Epson IC TRC CLK/CALENDAR</p>	 <p><b>RX-8035SA:AA PURE SN</b> Epson IC TRC CLK/CALENDAR</p>	 <p><b>RX-8035LC:AC3 PURE SN</b> Epson IC TRC CLK/CALENDAR</p>
 <p><b>RX-8035LC:B PURE SN</b> Epson IC TRC CLK/CALENDAR</p>	 <p><b>RX-8035LC:AC PURE SN</b> Epson IC TRC CLK/CALENDAR</p>	 <p><b>RX-8035SA:AA3: PURE SN</b> Epson IC RTC EVENT REC I2C 14-SOP</p>	 <p><b>RX-8035LC:AA3: PURE SN</b> Epson IC RTC EVENT REC I2C 12-VSOJ</p>

Hot Parts More

<ul style="list-style-type: none"> <li>⊕ 1206AA470KATBE</li> <li>⊖ C1005JB1V104M050BB</li> <li>⊕ CGA2B2X5R1H332K050BA</li> <li>D DMP4050SSS-13-F</li> <li>➔ GQM2195C2E2R0WB12D</li> <li>➔ IXFN280N07</li> <li>⊕ MDD600-20N1</li> <li>⊖ PI5C3245QEX</li> <li>⊕ SMBJ90CA-E3/52</li> <li>➔ TRS3223EIDBRG4</li> </ul>	<ul style="list-style-type: none"> <li>➔ 744042003</li> <li>⊕ C150AX12</li> <li>⊖ CGA2B3X8R1C333M050BE</li> <li>⊕ DS3231M+</li> <li>➔ GRM1555C1H6R8DA01J</li> <li>➔ J2-Q03B-D</li> <li>D MG150Q1J56SHA</li> <li>⊕ PQ48018HTA60NRS</li> <li>⊖ SMG2321P</li> <li>⊕ TSP5L40B</li> </ul>	<ul style="list-style-type: none"> <li>➔ ADC12048CIVF</li> <li>D CAT24WC256K-TE13</li> <li>⊕ CL10F105ZP8NNNC</li> <li>⊖ FZT749TC</li> <li>⊕ GRM2196T2A2R8CD01D</li> <li>D LH5116ZO</li> <li>➔ NFM41P11C204T1M00-54</li> <li>➔ S-93C46ADFJ-TB</li> <li>⊕ STM6718TGWY6F</li> <li>⊖ VI-J1Z-IY</li> </ul>	<ul style="list-style-type: none"> <li>D AP20G45H</li> <li>➔ CD4052BCMXX</li> <li>➔ CSR8510A04-ICXR-R</li> <li>⊕ GCM1885G1H821JA16D</li> <li>⊖ GTC1005P-2N7S</li> <li>⊕ LM201DR2G</li> <li>➔ NT68672UMFG</li> <li>➔ S908GZ48MFAE</li> <li>D TC74HC7266AF</li> <li>⊕ Z0803606PSC</li> </ul>	<ul style="list-style-type: none"> <li>➔ AP2314GN-HF</li> <li>➔ CD74ACT14M96</li> <li>➔ D3301N40T</li> <li>➔ GJM0335C1E4R9WB01D</li> <li>➔ IRKD270-12</li> <li>⊖ LTC6400IUD-26#TRPBF.</li> <li>➔ OPA330AIYFFR</li> <li>➔ SIHFR014</li> <li>➔ TPCA8006-H</li> <li>➔ ZXT13P12DE6TA</li> </ul>
---	--	---	--	---