


	<p><b>S-80141BLMC-JE2T2G</b></p>
	<p><b>Manufacturer Part Number:</b> S-80141BLMC-JE2T2G</p>
	<p><b>Manufacturer/Brand:</b> SII Semiconductor Corporation</p>
	<p><b>Part of Description:</b> IC VOLT DETECTOR 4.1V SOT23-5</p>
<p><b>Datasheets:</b>  <a href="#">S-80141BLMC-JE2T2G.pdf</a></p>	<p><b>RoHS Status:</b>  Lead free / RoHS</p>
<p><b>Stock Condition:</b> Compliant New original, Stock Available.</p>	<p><b>Ship From:</b> Hong Kong</p>
<p><b>Image may be representation. See specs for product details.</b></p>	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>









### Specifications

Part Number	S-80141BLMC-JE2T2G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.1V SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-801
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	65 ms Minimum
Voltage - Threshold	4.1V
Packaging	Tape & Reel (TR)

S-80141BLMC-JE2T2G is New Original in Stock, Search S-80141BLMC-JE2T2G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80141BLMC-JE2T2G SII Semiconductor Corporation with warrantied and confidence. RFQ S-80141BLMC-JE2T2G : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>S-80141BLPF-JE2TFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>	 <p><b>S-80141ANPF-JC2TFG</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>	 <p><b>S-80141ANPF-JC2TFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>	 <p><b>S-80141ANMC-JC2T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT23-5</p>
 <p><b>S-80141BNMC-JG2T2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT23-5</p>	 <p><b>S-80141BLMC-JE2T2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT23-5</p>	 <p><b>S-80141BNMC-JG2T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT23-5</p>	 <p><b>S-80141ALPF-JA2TFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>

### Hot Parts

More

- |                     |                     |                       |                     |                       |
|---------------------|---------------------|-----------------------|---------------------|-----------------------|
| ⚙️ 04025A3R9JAT2A   | 🔌 08051C332JAT4A    | ➡️ AD5680BRJZ-1500RL7 | D AD8225ARZ         | ➡️ AK4522VF-E2        |
| ⚡ AN8015SH-E1V      | ⚙️ AP1702GWL-7      | D AP2324GN            | ➡️ AT49LV002N-70VU  | ➡️ AT91SAM9G45-CU     |
| ⚙️ ATA2380LTHA-E    | ⚡ BUF420M(TO-3/CAN) | ⚙️ CL21B681KBANNNC    | 🔌 CMM6001-SC        | ➡️ CR10-000-ZK        |
| D EEE-HC1V100R      | ⚙️ FAN8413MX        | ⚡ FDS6984AS           | ⚙️ FM200TU-2A       | ➡️ FSA2156L6X         |
| ➡️ GAL18V10B-15LJN  | 🔌 HIP2100IBLF       | ⚙️ HMA2701R2          | ⚡ IRF6712STR1PBF    | ➡️ JS28F640P30B85     |
| 🔌 KSZ8721BLI-TR     | ➡️ LM26CIM5-VHA     | D LT3082ETS8#TRPBF    | ⚙️ MAX1910EUB+      | ⚡ MB3761PF-G-BND-ER   |
| ⚙️ MCF51AC128CCLKE  | D MCP111T-300E/TT   | ➡️ MDIS1502           | 🔌 MP7720DP          | ➡️ MTG200-06          |
| ⚡ MX7574JN+         | ⚙️ PBH-24-006       | 🔌 PI5C32384Q          | ➡️ PMPB12UN         | ➡️ QM30(50)DY-H       |
| ⚙️ RC1206FR-073K09L | ⚡ RT9163-33CXL      | ⚙️ SI3008FS           | D SP724AHTP         | ➡️ SPMWHT325AD5YBT0S0 |
| 🔌 SPP11N60C2        | ⚙️ STC3115IJT       | ⚡ TDA4856/V6          | ⚙️ TMP47C421AF-VA27 | ➡️ W0508RP040         |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited