

 Not Actual Photo YIC International Co., Limited.	<h2 style="color: red;">MSM8260-976NSP-TR-02-0</h2>													
	<table border="0"> <tr> <td>Manufacturer Part Number:</td> <td>MSM8260-976NSP-TR-02-0</td> </tr> <tr> <td>Manufacturer/Brand:</td> <td>QUALCOM</td> </tr> <tr> <td>Part of Description:</td> <td>QUALCOM BGA</td> </tr> <tr> <td>RoHs Status:</td> <td></td> </tr> <tr> <td>Stock Condition:</td> <td>New original, 1500 pcs Stock Available.</td> </tr> <tr> <td>Ship From:</td> <td>Hong Kong</td> </tr> <tr> <td>Shipment Way:</td> <td>DHL/Fedex/TNT/UPS/EMS</td> </tr> </table>	Manufacturer Part Number:	MSM8260-976NSP-TR-02-0	Manufacturer/Brand:	QUALCOM	Part of Description:	QUALCOM BGA	RoHs Status:		Stock Condition:	New original, 1500 pcs Stock Available.	Ship From:	Hong Kong	Shipment Way:
Manufacturer Part Number:	MSM8260-976NSP-TR-02-0													
Manufacturer/Brand:	QUALCOM													
Part of Description:	QUALCOM BGA													
RoHs Status:														
Stock Condition:	New original, 1500 pcs Stock Available.													
Ship From:	Hong Kong													
Shipment Way:	DHL/Fedex/TNT/UPS/EMS													
Image may be representation. See specs for product details.														

Specifications

Part Number	MSM8260-976NSP-TR-02-0
Manufacturer	QUALCOM
Description	QUALCOM BGA
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MSM8260-976NSP-TR-02-0 is New Original in Stock, Search MSM8260-976NSP-TR-02-0 Datasheets, PDF, Inventory at Y-IC.com Online, Order MSM8260-976NSP-TR-02-0 with warrantied and confidence. RFQ MSM8260-976NSP-TR-02-0 : Info@Y-IC.com

You May Be Also Be interested

In:

 MSM8260-1-976NSP-TR-01-0 QUALCOMM QUALCOMM BGA	 MSM8260A QUALCOM QUALCOM BGA	 MSM8260(MSM8260-1-976NSP-TR) QUALCOMM QUALCOMM BGA	 MSM8260(MSM8260-1-976NS) QUALCMM QUALCMM BGA
 MSM8260A-1VV QUALCOMM QUALCOMM SMD	 MSM8260-1-976NSP-TR-01- QUALCOM QUALCOM BGA	 MSM8274-1-990BPNSP-TR-01-0-AB QUALCOMM QUALCOMM BGA	 MSM8260-0-976NSP-TR-01-0-AA QUALCOMM QUALCOMM BGA

Hot Parts

More

- | | | | | |
|-----------------------|-------------------|--------------------|-----------------------|-----------------------|
| ⚙️ 08053A152GAT2A | ➡️ 1808CA222JAT1A | ➡️ 18122C473KAT2A | D 24LC00T-I/SN SOP8 | ➡️ AAT2608ALNJ-1-T1 |
| ⊖ ACT7807-25FN | ⚙️ APT20M18LVFR | D AT25010B-MAHL-T | ➡️ B82422A1333K108 | ➡️ BAS40CR1 |
| ⚙️ BAV21-TAP | ⊖ BC858BMTF | ⚙️ BZD27C91P-E3-08 | ➡️ BZX884-B20 | ➡️ CDBA340-G |
| D CL21C331FBANNNC | ⚙️ CM2860GSIM89TR | ⊖ CSTCE11M6G52-RO | ⚙️ DLW5BTN102SQ2L | ➡️ DT170N02KOF |
| ➡️ FF300R06KL | ➡️ FQD1N60C | ⚙️ FQI2N50TU | ⊖ FXLH1T45L6X | ➡️ GCM0335C1E6R0DD03D |
| ➡️ GRM1886R1H5R4DZ01D | ➡️ HSMP-3893-TR1 | D IRS2336DJPF | ⚙️ IXDD614SIA | ⊖ K6X4008C1F-VF55 |
| ⚙️ KSC945CLTA | D LM25062SQ/NOPB | ➡️ LM2717MT-ADJ | ➡️ LTC3411EMS#TRPBF | ➡️ MC100ES6254AC |
| ⊖ MCP23017T-E/SO | ⚙️ NSS20500UW3T2G | ➡️ PT7M820133TA3EX | ➡️ REG1117A-1.8/2K5G4 | ➡️ REG710NA-2.5/3K |
| ⚙️ RS3AB-13-F | ⊖ SIR428DP-T1-GE3 | ⚙️ SMBZ5933B | D SMF7V5A-M3-08 | ➡️ SP385ECA-L/TR |
| ➡️ SSCD102H | ⚙️ STB45N10L-TR | ⊖ UC2901DTR | ⚙️ V300C28C150AL2 | ➡️ XC62FP4202PR |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
 Copyright © 2019 YIC International Co., Limited