










	<p>S-80823CNNB-B8IT2G</p>
	<p>Manufacturer Part Number: S-80823CNNB-B8IT2G</p> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <p>Part of Description: IC VOLT DETECTOR 2.3V SC-82AB</p> <p>Datasheets:  S-80823CNNB-B8IT2G.pdf</p> <p>RoHs Status:  Lead free / RoHS Compliant</p> <p>Stock Condition: New original, 36520 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	S-80823CNNB-B8IT2G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 2.3V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	36520 pcs Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	2.3V
Packaging	Tape & Reel (TR)

































S-80823CNNB-B8IT2G is New Original in Stock, Search S-80823CNNB-B8IT2G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80823CNNB-B8IT2G SII Semiconductor Corporation with warrantied and confidence. RFQ S-80823CNNB-B8IT2G : Info@Y-IC.com

You May Be Also Be interested In:

 <p>S-80823CNNB-B8I-T2 SEIKO SEIKO SOT343</p>	 <p>S-80823CNNB-B8IT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.3V SC-82AB</p>	 <p>S-80823CNMC-B8I-T2 SEIKO SEIKO SOT153</p>	 <p>S-80823CNUA-B8I-T2 SEIKO S-80823CNUA-B8I-T2 SEIKO</p>
 <p>S-80823CNMC-B8IT2G SII Semiconductor Corporation IC VOLT DETECTOR 2.3V SOT23-5</p>	 <p>S-80823CNMC-B8I-G SEIKO SEIKO SOT-153</p>	 <p>S-80823CNPF-B8ITFU SII Semiconductor Corporation IC VOLT DETECTOR 2.3V SNT-4A</p>	 <p>S-80823CNUA-B8IT2G SII Semiconductor Corporation IC VOLT DETECTOR 2.3V SOT89-3</p>

Hot Parts

More

- | | | | | |
|--|--|---|--|--|
|  S-80822CNMC-B8HT2G |  S-80822CNNB-B8H-T2 |  S-80822CNNB-B8HT2G |  S-80822CNPF-B8HTFG |  S-80822CNUA-B8H-T2 |
|  S-80822CNUA-B8HT2G |  S-80823ALNP-EAL-T2 |  S-80823ALNP-EAL-T2G |  S-80823ALNP-EDL |  S-80823ALUP-EAL-T2 |
|  S-80823ALY-Z |  S-80823ANNP |  S-80823ANNP-EDL-T2 |  S-80823CLMC-B6I-T2 |  S-80823CLNB |
|  S-80823CLNB-B61-T2 |  S-80823CLNB-B6I-T1 |  S-80823CLNB-B6I2G |  S-80823CLNB-B6IT2G |  S-80823CLNB-B6IT2G |
|  S-80823CLUA-B6I-2 |  S-80823CLUA-B6I-T2 |  S-80823CLUA-B6IT2G |  S-80823CLY-B |  S-80823CNMC-B8IT2G |
|  S-80823CNUA-B8I-T2 |  S-80823CNUA-B8IT2G |  S-80823CNY |  S-80823CNY-Z |  S-80824ALNP |
|  S-80824ALNP-EAM-T2 |  S-80824ANMP-EDM-T2 |  S-80824ANNP |  S-80824ANNP-EDM-T2 |  S-80824CLMA-B6JT1G |
|  S-80824CLPF-B6JTFG |  S-80824CNMC-B8JT2G |  S-80824CNNB |  S-80824CNNB-B8J-T2G |  S-80824CNNB-B8JT2G |
|  S-80824CNUA-B8JT2G |  S-80824KNUA-D2B-T2 |  S-80824KNUA-D2BT2G |  S-80825ALUP-EAN-T2 |  S-80825ANMP-EDN-T2 |
|  S-80825ANNP |  S-80825ANNP-EDN-T2 |  S-80825ANNP-EDNT2G |  S-80825ANUP-EDN-T2 |  S-80825ANY-B |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited