










| | | |
|--|---|----------------------------------|
|  <p>A Renesas Company</p> | <h2 style="color: red;">X9261UV24</h2> | |
| | Manufacturer Part Number: | X9261UV24 |
|  | Manufacturer/Brand: | Intersil |
| | Part of Description: | IC XDCP DUAL 256TAP 50K 24-TSSOP |
| Datasheets: |  X9261UV24.pdf | |
| RoHs Status: | Contains lead / RoHS non-compliant | |
| Stock Condition: | New original, Stock Available. | |
| Ship From: | Hong Kong | |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS | |
| <p>Image may be representation. See specs for product details.</p> | | |

Specifications

| | |
|---------------------------------|---|
| Part Number | X9261UV24 |
| Manufacturer | Intersil |
| Description | IC XDCP DUAL 256TAP 50K 24-TSSOP |
| Category | Integrated Circuits (ICs) > Data Acquisition - Digital |
| Part Status | Require For Quote & Check Stock |
| Series | XDCP™ |
| Operating Temperature | 0°C ~ 70°C |
| Features | Selectable Address |
| Interface | SPI |
| Configuration | Potentiometer |
| Tolerance | ±20% |
| Package / Case | 24-TSSOP (0.173", 4.40mm Width) |
| Supplier Device Package | 24-TSSOP |
| Number of Circuits | 2 |
| Voltage - Supply | 5V |
| Memory Type | Non-Volatile |
| Resistance (Ohms) | 50k |
| Taper | Linear |
| Number of Taps | 256 |
| Temperature Coefficient (Typ) | ±300 ppm/°C |
| Resistance - Wiper (Ohms) (Typ) | 150 (Max) |
| Packaging | Tube |
























X9261UV24 is New Original in Stock, Search X9261UV24 Datasheets, PDF, Inventory at Y-IC.com Online, Order X9261UV24 Intersil with warrantied and confidence. RFQ X9261UV24 : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|--|
| <p>In:</p>  <p>X9261UV24I-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-TSSOP</p> |  <p>X9261US24Z-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p> |  <p>X9261UV24-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-TSSOP</p> |  <p>X9261US24Z Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p> |
|  <p>X9261UV24I Intersil IC XDCP DUAL 256TAP 50K 24-TSSOP</p> |  <p>X9261UV24-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-TSSOP</p> |  <p>X9261US24Z-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p> |  <p>X9261UV24I-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-TSSOP</p> |

Hot Parts

[More](#)

| | | | | |
|---|---|---|---|--|
|  A1212D-2W |  AD5171BRJ5-RL7 |  AP2602CMT-3 |  AT49BV160C-70CI |  C0402C0G1C4R3C |
|  C1005X5R0J684K050BB |  C1005X7R1V224K050BE |  C1005X8R2A681M050BA |  CEU4J2X7R1H683M125AE |  CV160-5-280 |
|  DD31N1600K |  DS90LV010ATM |  EH2625TTS-125.000M |  FDMS8560S |  FDS6614A |
|  FM21L16-60-TG. |  FQPF4N25 |  GBLC05CI-LF-T7 |  GL41M-E3/75 |  GRM1557U1H7R7C201D |
|  IRGSL4B60KD1 |  LA6548NHL-TE-L-E |  LM2937ES-15 |  LM380N/NOPB |  LT1121IST-3.3 |
|  LTC3406AES5#TRPBF |  MAX7461EUK |  MAX98090AETL+T |  MBRF30150CT |  MT46V16M16BG-6IT:F |
|  NLU2G06BMX1TCG |  PD55003STR-E |  PDS4200H-13 |  PK25FGG40 |  PS2761-1L-F3-A |
|  RPI-441C1E |  SH3003IMLTR |  SKY77177-11 |  SM4023NSKP-TRG |  SMCJ30CA-E3/57T |
|  SR170L-4R |  TC7USB221WBG |  TC7WGU04FC |  TD210N12KOF |  TDA8754HL/27 |
|  TPS65251-3RHAT |  UCC3921D/81143 |  UPC2771TB-E3-A |  VS-30ETH06STRLPBF |  ZXSBR16PT8TA |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited