













| | |
|--|--|
|  | BD7962FM-E2 |
| | Manufacturer Part Number: BD7962FM-E2 |
|  | Manufacturer/Brand: LAPIS Semiconductor |
| | Part of Description: IC BRIDGE DRIVER PAR 36HSOP |
| Datasheets:  BD7962FM-E2.pdf | RoHs Status:  Lead free / RoHS |
| Stock Condition: Compliant New original, 2676 pcs Stock Available. | Ship From: Hong Kong |
| Image may be representation. See specs for product details. | Shipment Way: DHL/Fedex/TNT/UPS/EMS |

Specifications

| | |
|----------------------------|---|
| Part Number | BD7962FM-E2 |
| Manufacturer | LAPIS Semiconductor |
| Description | IC BRIDGE DRIVER PAR 36HSOP |
| Category | Integrated Circuits (ICs) > PMIC - Full, Half-Bridge |
| Part Status | 2676 pcs Stock |
| Voltage - Supply | 4.5 V ~ 14 V |
| Voltage - Load | 6V |
| Technology | - |
| Supplier Device Package | 36-HSOP-M |
| Series | - |
| Rds On (Typ) | - |
| Packaging | Original-Reel® |
| Package / Case | 36-SOP (0.295", 7.50mm) + 2 Heat Tabs |
| Output Configuration | Half Bridge (12) |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Load Type | Inductive |
| Interface | Logic |
| Features | - |
| Fault Protection | Over Temperature |
| Current - Peak Output | - |
| Current - Output / Channel | - |
| Applications | DC Motors, General Purpose |

BD7962FM-E2 Electronic Components is 100% New Original from YIC Distributor, Search BD7962FM-E2 Datasheets, PDF, Inventory at Y-IC.com Online, Order BD7962FM-E2 LAPIS Semiconductor with Warrantied and Confidence. Ship by DHL/FedEx/TNT/UPS Express. Support Payment with Telegraphic Transfer(T/T) or PayPal.
RFQ BD7962FM-E2 Email: Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|---|
| <p>In:</p>  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7961FM ROHM BD7961FM ROHM</p> |  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7962FM ROHM BD7962FM ROHM</p> |  <p>BD7964FS-E2 Rohm Semiconductor IC MOTOR DRIVER PAR 5CH</p> |  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7964FS ROHM ROHM SSOP54</p> |
|  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7965FM ROHM BD7965FM ROHM</p> |  <p>BD7960FM-E2 Rohm Semiconductor IC MOTOR DRIVER PAR HSOP-M36</p> |  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7960FM ROHM BD7960FM ROHM</p> |  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BD7965FM-E2 ROHM BD7965FM-E2 ROHM</p> |

BD7962FM-E2 Related keyword

[More](#)

| | | | | |
|---|--|---|-----------------------------------|---|
| BD7962FM-E2 LAPIS Semiconductor | BD7962FM-E2 Data Sheet | BD7962FM-E2 Datasheets | BD7962FM-E2 PDF | LAPIS Semiconductor BD7962FM-E2 |
| BD7962FM-E2 Electronic | BD7962FM-E2 Components | BD7962FM-E2 Distributor | BD7962FM-E2 Image | BD7962FM-E2 Part |
| BD7962FM-E2 Price | BD7962FM-E2 Manufacturer | BD7962FM-E2 Picture | BD7962FM-E2 Stock | BD7962FM-E2 Inventory |
| BD7962FM-E2 New | BD7962FM-E2 Original | BD7962FM-E2 Warranted | BD7962FM-E2 RFQ | BD7962FM-E2 Order Online |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2020 YIC International Co., Limited