 <p>A Renesas Company</p>	<h2 style="color: red;">X40431V14-B</h2>	
	Manufacturer Part Number:	X40431V14-B
	Manufacturer/Brand:	Intersil
	Part of Description:	IC VOLT MON TRPL EEPROM 14-TSSOP
Datasheets:	 X40431V14-B.pdf	
RoHs Status:	Contains lead / RoHS non-compliant	
Stock Condition:	New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		









Specifications

Part Number	X40431V14-B
Manufacturer	Intersil
Description	IC VOLT MON TRPL EEPROM 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	3
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.7V, 2.6V, 4.4V
Packaging	Tube

X40431V14-B is New Original in Stock, Search X40431V14-B Datasheets, PDF, Inventory at Y-IC.com Online, Order X40431V14-B Intersil with warrantied and confidence. RFQ X40431V14-B : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40431S14I-CT1 Intersil IC VOLT MON TRPL EEPROM 14-SOIC</p>	 <p>X40431V14I-AT1 Intersil IC VOLT MON TRPL EEPROM 14-TSSOP</p>	 <p>X40431V14-AT1 Intersil IC VOLT MON TRPL EEPROM 14-TSSOP</p>	 <p>X40431V14-2.7 XICOR X40431V14-2.7 XICOR</p>
 <p>X40431V XICOR X40431V XICOR</p>	 <p>X40431V14I-A Intersil IC VOLT MON TRPL EEPROM 14-TSSOP</p>	 <p>X40431V14-C Intersil IC VOLT MON TRPL EEPROM 14-TSSOP</p>	 <p>X40431V14-A Intersil IC VOLT MON TRPL EEPROM 14-TSSOP</p>

Hot Parts

More

- | | | | | |
|----------------------|------------------|-------------------|-----------------|-----------------|
| 06031A180K4T2A | 06035F102KAT2A | 12066C226MAT2A | A6300E5VR-33 | AK2210-L |
| AM29F080B-120SCT | B2405S-2WR2 | B39242-AA38A-P810 | BD2232G-GTR | CL21B201KBANNNC |
| CR60-080 | CS410899B | CY7C185-15VI | DFLS240L-7-F | DS1990R#F3 |
| EMK063B7152KP-F | F1206SB1000V063T | FCPF190N60 | FRG25AA80 | G5PA-1-M-E-5VDC |
| GCM21A7U2E122JX01D | IPW60R190E6 | IPW90R1K2C3 | IRF740AL | IRFW550ATM |
| IRLU8711CPBF | L1117H-18A72R | LD3985J28 | LMBTH10LT1G | LQP15MN18NG02D |
| M1/DF60-16 | MCT06P10 | MDA810-16N1 | P6KE170A | PAM3115ABA120 |
| PCA9530DR | PI3B3126QE | PX075FD28K | RK73H3ATTE10R7F | RSS090N03TB |
| SAH-XC2361A-56F80L34 | SCF5251VM | SMAJ13CA-E3/61 | SMBJ130CA | T1971N40TOH |
| TLC1543CDBR | TPA6047A4RHBR | TSD180N10 | TTB6C135N02LOF | XBP1007-G |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited