	<h2 style="color: red;">74HC393BQ</h2>
	<p>Manufacturer Part Number: 74HC393BQ</p> <p>Manufacturer/Brand: NXP</p> <p>Part of Description: 74HC393BQ NXP</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 22646 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	74HC393BQ
Manufacturer	NXP
Description	74HC393BQ NXP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	22646 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

74HC393BQ is New Original in Stock, Search 74HC393BQ Datasheets, PDF, Inventory at Y-IC.com Online, Order 74HC393BQ with warrantied and confidence. RFQ 74HC393BQ : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>74HC393BQ,115 Nexperia IC DUAL 4BIT BINAR RIPP 14DHVQFN</p>	 <p>74HC393D Original</p>	 <p>74HC393D Toshiba Semiconductor and Storage IC DUAL 4BIT BINARY COUNT 14SOIC</p>	 <p>74HC393A Toshiba Semiconductor and Storage 74HC393A TOSHIBA</p>
 <p>74HC393AP TOS TOS DIP14</p>	 <p>74HC393BQ-Q100X Nexperia IC DUAL 4BIT BINAR RIPP 14DHVQFN</p>	 <p>74HC393ADR2 MOT/ON MOT/ON SOP3.9</p>	 <p>74HC393AF TOS TOS SOP</p>

Hot Parts

[More](#)

- | | | | | |
|---------------------|--------------------|--------------------|-----------------------|-----------------------|
| ⚙️ 06033A8R0DAT2A | ➡️ 1808AA102MATRE | ➡️ ADP3405ARU | D ADS7951SBDBTR | ➡️ ATA5021-TAQY |
| ⚡️ ATD975C3202-X1AC | ⚙️ B220-13-F | D C3216X7R2J103K | ➡️ CD74HCT163M96 | ➡️ CM150RX1-12A |
| ⚙️ EL2070CS | ⚡️ EM-6781-T3 | ⚙️ FQD7P20TM_F080 | ➡️ GCM31CR71A685KA64L | ➡️ KASCHKE35/98 |
| D LC74788JM-9696 | ⚙️ LM2674M-ADJ | ⚡️ LM2904PT | ⚙️ LP2951CMMX-3.0 | ➡️ LW010A8J81 |
| ➡️ MAX14780EEPA | ➡️ MAX6381XR17D2+T | ⚙️ MAX8529EEG | ⚡️ MMBF4119 | ➡️ NCP4200MNR2G |
| ➡️ NFC10-9502 | ➡️ NRF24LE1I | D NTCG104BF473HT1X | ⚙️ NTD3055L170T4 | ⚡️ PCM1780DBQRG4 |
| ⚙️ PM8303A-WGI | D QS3390QX | ➡️ R2J20601NPEB | ➡️ RC0603JR-1068K | ➡️ REG1117A-2.5/2K5G4 |
| ⚡️ SGH10N60RUFDTU | ⚙️ SI-8050HFE | ➡️ SN74ACT573DBR | ➡️ SS1030FL-T3 | ➡️ SUP75N03-07-E3 |
| ⚙️ TAJA225M016RNJ | ⚡️ TEA1061/C1 | ⚙️ TEA1062AT | D TLE5205S | ➡️ TLV71325PDQNR |
| ➡️ TS5A1066DCKR | ⚙️ TT61N16LOF | ⚡️ UVK105CH5R1JW-F | ⚙️ VI-J03-IY | ➡️ VI-J1L-CW |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited