



LAPIS Semiconductor



YIC International Co., Limited.

Image may be representation.
See specs for product details.

BU4235F-TR

| | |
|----------------------------------|---|
| Manufacturer Part Number: | BU4235F-TR |
| Manufacturer/Brand: | LAPIS Semiconductor |
| Part of Description: | IC DETECTOR VOLT 3.5V ODRN 4SOP |
| Datasheets: | BU4235F-TR.pdf |
| RoHs Status: | Lead free / RoHS |
| Stock Condition: | Compliant New original, 200 pcs Stock Available. |
| Ship From: | Hong Kong |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS |

Specifications

| | |
|------------------------------|--|
| Part Number | BU4235F-TR |
| Manufacturer | LAPIS Semiconductor |
| Description | IC DETECTOR VOLT 3.5V ODRN 4SOP |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | 200 pcs Stock |
| Series | - |
| Operating Temperature | -40°C ~ 125°C (TA) |
| Mounting Type | Surface Mount |
| Type | Simple Reset/Power-On Reset |
| Package / Case | SC-82 |
| Supplier Device Package | 4-SOP |
| Output | Open Drain or Open Collector |
| Reset | Active Low |
| Number of Voltages Monitored | 1 |
| Reset Timeout | Adjustable/Selectable |
| Voltage - Threshold | 3.5V |
| Packaging | Tape & Reel (TR) |

BU4235F-TR is New Original in Stock, Search BU4235F-TR Datasheets, PDF, Inventory at Y-IC.com Online, Order BU4235F-TR LAPIS Semiconductor with warrantied and confidence. RFQ BU4235F-TR : Info@Y-IC.com

You May Be Also Be interested

In:



BU4236FVE-TR
LAPIS Semiconductor
IC RESET N-CH OD 3.6V 5VSOF



BU4234F-TR
LAPIS Semiconductor
IC DETECTOR VOLT 3.4V ODRN 4SOP



BU4234G-TR
LAPIS Semiconductor
IC DETECTOR VOLT 3.4V ODRN 5SSOP



BU4236G-TR
LAPIS Semiconductor
IC DETECTOR VOLT 3.6V ODRN 5SSOP



BU4233FVE-TR
LAPIS Semiconductor
IC RESET N-CH OD 3.3V 5VSOF



BU4234FVE-TR
LAPIS Semiconductor
IC RESET N-CH OD 3.4V 5VSOF



BU4235G-TR
LAPIS Semiconductor
IC DETECTOR VOLT 3.5V ODRN 5SSOP



BU4235FVE-TR
LAPIS Semiconductor
IC RESET N-CH OD 3.5V 5VSOF

Hot Parts

More

| | | | | |
|--------------------|--------------------|-----------------------|--------------------|--------------------|
| 06035A100GAT2A | 08055C224KAT2A | 12063C274KAT2A | 12104D107KAT2A | 1808GC471ZAT1A |
| 528931696 | AAT3673IXN-4.2-1 | BH6578FVM-FTR | CDRH8D43-6R8 | EGL41C-E3/96 |
| FF900R12IE4 | GRM0335C2A9R6DA01J | GRM1556S1HR90BD01D | GRM2165C1H220FZ01J | GRM32RR11H105KA01L |
| HCPL0501SR2M | IRFB7437GPBF | LD031A220FAB2A | LPC1114FHN33/301:5 | LTC1387CSW |
| LTC3421EUF#PBF | MA3036-H | MDD19-06N1B | MK1491E-14R | MM3511C46YRE |
| MT41K512M8DA-107:P | N540CH12HOO | NFM41R01C1001T1M00-54 | NP90N055MUK | NR4012T3R3M |
| NS6A5.0AT3G | PO48F048T241F | PS48M2V5DCS | RHRG75120 | RJK6026DPP-MZ-T1 |
| S-817A30APF-CU | SF100U27 | SMF48CAT1G | SN74LVT16244BDGGR | SQ2389ES-T1-GE3 |
| SR202AM-40S | SR69R006F1N | SST10LM11-MVQF-MM006 | STL6251-1H4FD | TL431BQLPR |
| TLV2264AQPWRQ1 | UPC3245TB-E3 | VOM618A-1T | XC6209B502MR-G | XC9236B33DMR |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited