

	<h2 style="color: red;">SLA7075MR</h2>	
	Manufacturer Part Number:	SLA7075MR
	Manufacturer/Brand:	Sanken Electric Co., Ltd.
	Part of Description:	IC MOTOR BRIDGE PAR 23SIP
Datasheets:	1.SLA7075MR.pdf 2.SLA7075MR.pdf	
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	


Specifications

Part Number	SLA7075MR
Manufacturer	Sanken Electric Co., Ltd.
Description	IC MOTOR BRIDGE PAR 23SIP
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	-
Technology	Power MOSFET
Operating Temperature	-20°C ~ 150°C (TJ)
Mounting Type	Through Hole
Interface	Parallel
Applications	General Purpose
Package / Case	23-SSIP, Exposed Tab, Formed Lead
Supplier Device Package	23-SLA
Voltage - Supply	3 V ~ 5.5 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	1A
Output Configuration	Low Side (4)
Voltage - Load	10 V ~ 44 V
Motor Type - Stepper	Unipolar
Motor Type - AC, DC	-
Step Resolution	1, 1/2, 1/4, 1/8, 1/16
Packaging	Tube


SLA7075MR is New Original in Stock, Search SLA7075MR Datasheets, PDF, Inventory at Y-IC.com Online, Order SLA7075MR Sanken Electric Co., Ltd. with warrantied and confidence. RFQ SLA7075MR : Info@Y-IC.com

You May Be Also Be interested


In:




SLA7073MS
Sanken Electric Co., Ltd.
IC MOTOR DRIVER ZIP




SLA7076MPRT
Sanken Electric Co., Ltd.
IC MOTOR DRIVER PAR 23SLA




SLA7075MPR
Sanken Electric Co., Ltd.
IC MOTOR BRIDGE PAR 23SIP




SLA7073MR
Sanken Electric Co., Ltd.
IC MOTOR BRIDGE PAR 23SIP




SLA7076MR
Sanken Electric Co., Ltd.
IC MOTOR BRIDGE PAR 23SIP



SLA7077MPR
Sanken Electric Co., Ltd.
IC MOTOR DRIVER PAR 23SLA



SLA7073MS LF2151
Sanken Electric Co., Ltd.
IC MOTOR BRIDGE PAR 23SIP



SLA7077MPRT
Sanken Electric Co., Ltd.
IC MOTOR DRIVER PAR 23SLA

Hot Parts More

- | | | | | |
|--------------------|------------------------|------------------------|----------------------|------------------------|
| ⚙️ 08055A331GAT2A | ↔️ 2MBI450VJ-120-85 | ⇒ 79RTA120 | D ADM6384YKS23D3Z-R7 | ⇒ BAT54-02V-V-G-08 |
| ⊖ BU8272GUW-E2 | ⚙️ C4532X7R2J104K230KA | D CGA2B2X8R2A152M050BA | ⇒ CL31A106KPHNNNF | ⇒ CY7C1021DV33-10ZSXIT |
| ⚙️ DF100R12KF-A | ⊖ DS90LV019TM | ⚙️ EP3C5F256I7N | ↔️ ETK4863M | ⇒ FDP18N50 |
| D ICP-S2.3TN | ⚙️ IRLI3705N | ⊖ ISL6557ACB | ⚙️ KA5L0365RYDTU | ⇒ LB1960M-TLM |
| ⇒ LDA213G1910F-292 | ↔️ LT1786FCS#PBF | ⚙️ LT3757AEMSE#PBF | ⊖ LTC5587IDD#PBF | ⇒ M29W640GB90NA6E |
| ↔️ MA6161-23 | ⇒ MAX3221CUE+T | D MAX5900AAEUT-T | ⚙️ MC34063ABD-TR | ⊖ MTB11N03CQ8 |
| ⚙️ NNCD6.8G-T1 | D OPA2211AIDAR | ⇒ P6SMB250A-E3/52 | ↔️ PS1080-A2 | ⇒ R2A20010NP |
| ⊖ RGF1A-E3/67A | ⚙️ S30-A90X | ↔️ SMS3925-040LF | ⇒ SN74LVC2G74YZPR | ⇒ SSM6L36FE |
| ⚙️ TA1276AN | ⊖ TDA3664AT/N1 | ⚙️ TDE1747FPT | D TLV2302IDR | ⇒ TMS320C6414TBGLZA6 |
| ↔️ TPS3808G125DBVR | ⚙️ UFM718TA | ⊖ UMK105CG430JV-F | ⚙️ WR06X392JTL | ⇒ XC6221B332MR |