









 <p>A Renesas Company</p>	<p><b>ISL3155EUIZ-T</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL3155EUIZ-T</a></p> <hr/> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <hr/> <p><b>Part of Description:</b> IC TXRX RS422/485 1MBPS 8MSOP</p> <hr/> <p><b>Datasheets:</b>  <a href="#">ISL3155EUIZ-T.pdf</a></p> <hr/> <p><b>RoHs Status:</b>  Lead free / RoHS</p> <hr/> <p><b>Stock Condition:</b> Compliant New original, 3000 pcs Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	<a href="#">ISL3155EUIZ-T</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC TXRX RS422/485 1MBPS 8MSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; Interface - Drivers, Receivers,</a>
Part Status	3000 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	20mV
Data Rate	1Mbps
Packaging	Tape & Reel (TR)


























ISL3155EUIZ-T is New Original in Stock, Search ISL3155EUIZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL3155EUIZ-T Intersil with warrantied and confidence. RFQ  
ISL3155EUIZ-T : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p>In:</p>  <p><b>ISL3155EIBZ-T7A</b> Intersil IC TXRX RS422/RS485 8SOIC</p>	 <p><b>ISL3156EUIZ</b> Intersil IC TXRX RS422/485 20MBPS 10MSOP</p>	 <p><b>ISL3156EIBZ</b> Intersil IC TXRX RS422/485 20MBPS 14SOICN</p>	 <p><b>ISL3156EIBZ-T</b> Intersil IC TXRX RS422/485 20MBPS 14SOICN</p>
 <p><b>ISL3155EIBZ-T</b> Intersil IC TXRX RS422/485 1MBPS 8SOIC</p>	 <p><b>ISL3155EIBZ</b> Intersil IC TXRX RS422/485 1MBPS 8SOIC</p>	 <p><b>ISL3156EIBZ-T7A</b> Intersil IC TXRX RS422/RS485 14SOIC</p>	 <p><b>ISL3155EUIZ-T7A</b> Intersil IC TXRX RS422/RS485 8MSOP</p>

### Hot Parts

[More](#)

 5STP50Q1800	 6RI100G-040	 AD1980JSTZ	 AEE03A18	 BC848AMTF
 BL9193-33BAPURN	 BM1117-ADJ	 BZX55C68-TAP	 BZX84C24W-7-F	 C358PBX95
 CM36686CM3OI-H1	 DRQ73-102-R	 FDMS8558SDC	 GA100LS120K	 IPS2051LTRPBF
 IXFK180N10	 IXTA110N055P	 K9F8G08U0M-PIB0	 KST10MTF	 LT1253CS8
 LTC3409IDD#TRPBF	 LTC6081IDD#TRPBF	 M38223M4L-304HP	 MAX5477ETE	 MAX9304GGM/VY+T
 MBM29LV800BE-60PFTN	 MC12034ADR2G	 MCO500-18I01	 N1132NC360	 NCP130AMX105TCG
 NTD4808N	 P1100SALRP	 P214CH04FLO	 PS5020-100MT	 R5325K006B-TR
 S-80921CNMC-G8R-T2	 SK30GB123	 SMAJ40AHE3/61	 SMBJ6.5A	 SMV1705-999
 SOMC1601-101G	 SOMC160322K0GDC	 SQ48S10050-NS00GR	 T931S18TKN	 TMK107BJ224KA-T
 TPD4E001DRLR	 VI-222-CY	 VN5E050AJ-E	 VS-8E2TX06-M	 YNA21B2J0G106M

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited