

	<h2 style="color: red;">IDT2308A-4DCI</h2>	
	Manufacturer Part Number:	IDT2308A-4DCI
	Manufacturer/Brand:	IDT (Integrated Device Technology)
	Part of Description:	IC CLOCK MULT ZD STD DRV 16-SOIC
Datasheets:	 IDT2308A-4DCI.pdf	
RoHs Status:	Contains lead / RoHS non-compliant	
Stock Condition:	New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications	
Part Number	IDT2308A-4DCI
Manufacturer	IDT (Integrated Device Technology)
Description	IC CLOCK MULT ZD STD DRV 16-SOIC
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Multiplier, Zero Delay Buffer
Frequency - Max	133.3MHz
Package / Case	16-SOIC (0.154", 3.90mm Width)
Supplier Device Package	16-SOIC
Number of Circuits	1
Voltage - Supply	3 V ~ 3.6 V
Output	LVTTL
Input	LVTTL
PLL	Yes with Bypass
Ratio - Input:Output	1:8
Differential - Input:Output	No/No
Divider/Multiplier	No/Yes
Packaging	Tube

IDT2308A-4DCI is New Original in Stock, Search IDT2308A-4DCI Datasheets, PDF, Inventory at Y-IC.com Online, Order IDT2308A-4DCI IDT (Integrated Device Technology) with warrantied and confidence. RFQ IDT2308A-4DCI : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>IDT2308A-5HDCI8 IDT (Integrated Device Technology) IC CLOCK MULT ZD HI DRV 16-SOIC</p>	 <p>IDT2308A-4DCI8 IDT (Integrated Device Technology) IC CLOCK MULT ZD HI DRV 16-SOIC</p>	 <p>IDT2308A-4DC IDT (Integrated Device Technology) IC CLOCK MULT ZD STD DRV 16-SOIC</p>	 <p>IDT2308A-3DCI8 IDT (Integrated Device Technology) IC CLOCK MULT ZD STD DRV 16-SOIC</p>
 <p>IDT2308A-5HDCI IDT (Integrated Device Technology) IC CLOCK MULT ZD HI DRV 16-SOIC</p>	 <p>IDT2308A-5HDC8 IDT (Integrated Device Technology) IC CLOCK MULT ZD HI DRV 16-SOIC</p>	 <p>IDT2308A-3HDCGI IDT IDT SOP16</p>	 <p>IDT2308A-3HDCG IDT IDT2308A-3HDCG IDT</p>

Hot Parts

More

- | | | | | |
|-----------------------|----------------------|----------------------|---------------------|------------------|
| ⊕ 0201ZA6R8CAT2A | ↔ 0805YD105MA12A | ⇒ 2220HA121JAT1A | D ACE507A25BM+H | ↔ AD22226B62 |
| ⊖ B240LA-13 | ⊕ BFC233920104 | D BU16501KS2-E2 | ⇒ CC0402DRNPO9BN6R8 | ↔ CY24204ZXC-3T |
| ⊕ CY7C1041CV33-10BAIT | ⊖ DG3535DB-T1-E1 | ⊕ DS3231SN+T | ↔ FDV305N-NL | ↔ FQD12N20L |
| D GRM1557U1H8R2CZ01D | ⊕ GRM2166R1H120JZ01D | ⊖ IHLP2525CZER220M11 | ⊕ IRLR3303TRR | ↔ LC89056W-E |
| ⇒ LL1005-FHL33NJ | ↔ LL2012-FHR27J | ⊕ LL2012-HF3N9S | ⊖ LM5025BMTCX | ↔ LM75CIM-3/NOPB |
| ↔ LMV1015URX-15 | ⇒ LT1882IS#TRPBF | D MAX6339IUT-T | ⊕ MAX8796G | ⊖ MAZ80680L |
| ⊕ MC9S08SE4VTG | D MIC2941BU | ⇒ MMSZ3V9T1 | ↔ MTC55A1600V | ↔ MURHS160T3G |
| ⊖ NCP15XM331J03RC | ⊕ P6SMB160AT3G | ↔ PAC107BBA | ⇒ PT7A7514WEX | ↔ PTMB75B12C |
| ⊕ QM50D1X-H | ⊖ RC0805JR-0722RL | ⊕ S-80827ALNP-EAQ-T2 | D SC5205-5.0CSKTR | ↔ SMBJ30CA-E3/52 |
| ↔ SP1485EMN-L | ⊕ TFL0816-18N | ⊖ TNY256YN | ⊕ VE-2N2-EU | ↔ VI-J51-06 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited