









	<h2 style="color: #E67E22;">ZL40220LDF1</h2>	
	Manufacturer Part Number:	ZL40220LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFFER 2:6 750MHZ 32QFN
	Datasheets:	1.ZL40220LDF1.pdf 2.ZL40220LDF1.pdf 3.ZL40220LDF1.pdf
	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
	Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.		

Specifications

Part Number	ZL40220LDF1
Manufacturer	Microsemi
Description	IC CLK BUFFER 2:6 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVDS
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	2:6
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40220LDF1 is New Original in Stock, Search ZL40220LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40220LDF1 Microsemi with warrantied and confidence. RFQ
 ZL40220LDF1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ZL40218LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40222LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40218LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40220LDG1 Microsemi IC CLK BUFFER 2:6 750MHZ 32QFN</p>
 <p>ZL40222LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40221LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40219LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40217LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>

Hot Parts

More

- | | | | | |
|------------------------|------------------|-------------------|------------------------|-------------------|
| # 08051A2R0JAT2A | ↔ 08052U680FAT2A | ⇒ BA3257HFP-TR | D BQ20Z70PWR-V150 | ⇒ CAT93C46LI-G |
| ↳ CGA8L2X7R1H225K160KA | # DD241S04K | D DFLS2100-7 | ⇒ DT142N12 | ⇒ FDC607AN_NL |
| # GRM188R72A332KA01J | ↳ IP-220CW | # IPP60R160C6 | ↔ IRF19Z24GPBF | ⇒ IRLR7821TRPBF. |
| D KC224550 | # LH1511AB | ↳ LP3987H-33B5F | # LP3988ITLX-2.85/NOPB | ⇒ LT3685EDD |
| ⇒ LT5525EUF#PBF | ↔ MAX15059AATE+T | # MBR2035CTPBF | ↳ MC14071BFEL | ⇒ MC145407P |
| ↔ MG200N1US41 | ⇒ MIC2214-GKYML | D MP20041DGT-LF-Z | # MT48V8M32LFF5-8 | ↳ NET2280REV1A-LF |
| # OB3613PAP | D PHY1078-01 | ⇒ PKFC05C-T75 | ↔ PRZ1452V15PP5U | ⇒ PS2501-1SM |
| ↳ PS2566-4 | # RSB6.8SMT2N | ↔ RT8251GSP | ⇒ SKIIP31NAB12T49 | ⇒ SMBJ64CA |
| # SPX1585AT-L/TR | ↳ TCA0G107M8R-02 | # TLE4473G55-2 | D TPSMC30A-E3 | ⇒ TSX634IQ4T |
| ↔ UPC8151TB | # VI-J22-CX | ↳ VT030-04D01 | # XCR3256XL-12CS280C | ⇒ XM0825SF-TL1301 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited