

	<p>CY7C68320-100AXC</p>
	<p>Manufacturer Part Number: CY7C68320-100AXC</p>
	<p>Manufacturer/Brand: Cypress Semiconductor</p>
	<p>Part of Description: IC USB 2.0 BRIDGE AT2LP 100LQFP</p>
	<p>Datasheets:  CY7C68320-100AXC.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, 7 pcs Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	CY7C68320-100AXC
Manufacturer	Cypress Semiconductor
Description	IC USB 2.0 BRIDGE AT2LP 100LQFP
Category	Integrated Circuits (ICs) > Interface - Controllers
Part Status	7 pcs Stock
Series	EZ-USB AT2LP™
Current - Supply	50mA
Operating Temperature	0°C ~ 70°C
Interface	ATA
Package / Case	100-LQFP
Supplier Device Package	100-TQFP (14x20)
Voltage - Supply	3.15 V ~ 3.45 V
Standards	USB 2.0
Function	Bridge, USB to ATA
Protocol	USB
Packaging	Tray

CY7C68320-100AXC is New Original in Stock, Search CY7C68320-100AXC Datasheets, PDF, Inventory at Y-IC.com Online, Order CY7C68320-100AXC Cypress Semiconductor with warrantied and confidence. RFQ CY7C68320-100AXC : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>CY7C68320-56LFXC Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 56VQFN</p>	 <p>CY7C68310-80AC Original CY7C68310-80AC Original</p>	 <p>CY7C68320C-100AXAT Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 100LQFP</p>	 <p>CY7C68320C-100AXC Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 100LQFP</p>
 <p>CY7C68301C-56LFXC Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 56VQFN</p>	 <p>CY7C68320C-100AXA Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 100TQFP</p>	 <p>CY7C68301C-56LTXC Cypress Semiconductor IC USB 2.0 BRIDGE AT2LP 56VQFN</p>	 <p>CY7C68310-80AXC CYPRESS CYPRESS QFP</p>

Hot Parts

More

- | | | | | |
|---|--|--|---|---|
|  0603YA4R3JAT2A |  1812CC103KA1ME |  AD8342ACPZ-REEL7 |  AMC2576-5.0PF |  B39202-B7801-A510 |
|  BZT52H-C62 |  C2220X103K202T |  CGJ4J2X7R1C474K125AA |  CL10C560FB8NNNC |  CS284-48I01 |
|  DT61N10K0F |  E15NA100 |  EMGE31-12 |  ESDA6V1-5W6 |  FSEZ1317WAMY |
|  D HCF4025BEY |  HD64540CP |  IR2213SPBF |  IRKC71-04 |  ISL6525CB-T |
|   L79L15ACD13TR |   LT4250LIS8#TRPBF |  MAX64180CXO+ |   MAX9003EUA+T |  MAZS3000HL |
|   MB89061PF-G-121-BND |   MC34166TG |  MI-261-IW |  MIC2937A-12WU |   MICROSM005F-02 |
|  MMBZ5222B-7-F |  MT29F32G08CBACAWP-IT:C |   NCT6795D-M |   OPA2631U/2K5 |   PCM1608KY/2K |
|   PF0464-223T |  PH150F110-2 |   R0487YS10F |   RJK03J6DPA-00#J5A |   RSS050P03FU06TB |
|  RT9182APES |   S-24CS08AFJ-TB |  S29GL512S11DHB020 |  SFT1423-TL-E |   SKT450/18E |
|   TT170N17L9 |   VI-J5Z-CY |   VI-J62-IW/F3 |  VS-8EWS08STRPBF |   XC9111C501MR |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited