




	<h2 style="color: red;">BU4219FVE-TR</h2>
	<p><b>Manufacturer Part Number:</b> BU4219FVE-TR</p> <p><b>Manufacturer/Brand:</b> LAPIS Semiconductor</p> <p><b>Part of Description:</b> IC DETECTOR VOLT 1.9V ODRN 5VSOF</p> <p><b>Datasheets:</b>  <a href="#">BU4219FVE-TR.pdf</a></p> <p><b>RoHs Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	BU4219FVE-TR
Manufacturer	LAPIS Semiconductor
Description	IC DETECTOR VOLT 1.9V ODRN 5VSOF
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SOT-665
Supplier Device Package	5-VSOF
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.9V
Packaging	Tape & Reel (TR)

BU4219FVE-TR is New Original in Stock, Search BU4219FVE-TR Datasheets, PDF, Inventory at Y-IC.com Online, Order BU4219FVE-TR LAPIS Semiconductor with warrantied and confidence.  
RFQ BU4219FVE-TR : Info@Y-IC.com

### You May Be Also Be interested

<p>In:</p>  <p><b>BU4221F</b> ROHM BU4221F ROHM</p>	 <p><b>BU4217G-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.7V ODRN 5SSOP</p>	 <p><b>BU4218G-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.8V ODRN 5SSOP</p>	 <p><b>BU4218F-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.8V ODRN 4SOP</p>
 <p><b>BU4220FVE-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 2.0V ODRN 5VSOF</p>	 <p><b>BU4219F-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.9V ODRN 4SOP</p>	 <p><b>BU4218FVE-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.8V ODRN 5VSOF</p>	 <p><b>BU4219G-TR</b> LAPIS Semiconductor IC DETECTOR VOLT 1.9V ODRN 5SSOP</p>

### Hot Parts

More

04025A220JA2A	08053E103ZAT2A	08055A151KAT9A	2225HC472KAT3A\SB	2RI100G-160X2PX3
AD8517ART-RL7	BAS70-06-7-F	BTA1664L3	CL05C100JB5NNND	CL10C180JB81PNC
CM2854IM26TR	EMK042CG4R7BC-FW	EP10QY03-TE8L3	FAN3100TMPX	FDA59N25
FP30R06WE3ENG	GCE216R71H22KA01D	GRM0225C1E330GA02L	GRM31A5C2J560JW01D	IA2415S-2W
ICL3232ECAZ	IDT7134SA70J	IRFB4610PBF	ISL6540AIRZ	ISL84541CB-T
L512F-8547	LP3918TL-A/NOPB	MAX1606EUA+T	MCD40-12	MIC4428BM
MMD70R1K4PBRH	N980CH160	PD333-3C/L2	RT9701CB	S-24CM01CI-J8T1U4
SDIN5D2-2G	SMF18A-R1-00001	SN74GTL16616DLR	SN75107BDR	SN75ALS174ADWR
SP6137CU-L	SPMC65SF112A-001D	SSG300C120	STC3265Y	STD3NK80ZT4
T236N20EOC	TPS3809J25DBVRG4	TPS79428DGNR	TTB6C165N14LOF	W9812G2DB-75

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited