


	<b>PL502-05SC</b>
	<b>Manufacturer Part Number:</b> PL502-05SC <b>Manufacturer/Brand:</b> Micrel / Microchip Technology <b>Part of Description:</b> IC VCXO 25MHZ 8SOIC <b>RoHs Status:</b>  Lead free / RoHS <b>Stock Condition:</b>  New original, Stock Available. <b>Ship From:</b> Hong Kong <b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS
	
<p>Image may be representation. See specs for product details.</p>	


**Specifications**








Part Number	PL502-05SC
Manufacturer	Micrel / Microchip Technology
Description	IC VCXO 25MHZ 8SOIC
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	*
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

PL502-05SC is New Original in Stock, Search PL502-05SC Datasheets, PDF, Inventory at Y-IC.com Online, Order PL502-05SC Micrel / Microchip Technology with warranted and confidence.  
RFQ PL502-05SC : Info@Y-IC.com

You May Be Also Be interested

In:



<p><b>PL502-11OCL</b> PhaseLink PL502-11OCL PhaseLink</p>	 <p><b>PL502-04SC-R</b> Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p><b>PL502-11OC-R</b> Micrel / Microchip Technology IC VCXO 25MHZ 16TSSOP</p>	 <p><b>PL502-02SC-R</b> Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>
 <p><b>PL502-03SC-R</b> Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p><b>PL502-05SC-R</b> Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p><b>PL502-04SC</b> Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p><b>PL502-30DC</b> Micrel / Microchip Technology IC VCXO</p>

Hot Parts

More

- |                       |                        |                 |                   |                       |
|-----------------------|------------------------|-----------------|-------------------|-----------------------|
| ⊛ 0805YC822JAT2A      | ↔ 12067C182MAT2A       | ⇒ 150KR20AM     | D 6DI100A-050P    | ⇒ 744043330           |
| ⊣ AD8048ARZ           | ⊛ AOWF11S65            | D BSP297L6327   | ⇒ BSTN35110       | ⇒ C1005X7S0G105M050BC |
| ⊛ DCR504ST0606        | ⊣ DM74AS652NT          | ⊛ E3Z-R81HK     | ↔ FQD2N60TM       | ⇒ GRM0335C1H8R5BD01D  |
| D HFA1106IBA          | ⊛ HW-101/D             | ⊣ iD9302-33B30R | ⊛ IR2110L4        | ⇒ IRFS7440TRPBF       |
| ⇒ IS64LV6416AL-20TLA3 | ↔ KC7050P125.000P30E00 | ⊛ KSB1121STF    | ⊣ LD2985BM30R     | ⇒ LDA312G9813F-239    |
| ↔ LM2594MX-5.0        | ⇒ LMK107B7474KAHT      | D LP3990IL-2.8  | ⊛ MAX1775EEE      | ⊣ MAX324CUA+          |
| ⊛ MAX4766CETA+TG126   | D MAX6009BEUR-TG096    | ⇒ MB84256A-70L  | ↔ MBR3045CT-E3/45 | ⇒ MCC162-14           |
| ⊣ ML6206P502MRG       | ⊛ P6SMB350A            | ↔ PPD1R5-48-15  | ⇒ RTPXA320B2E806  | ⇒ S10B-ZR-SM3A-TF     |
| ⊛ SFH3201-3           | ⊣ SFH610A-1X001        | ⊛ SHF-0289      | D SKKD500-12      | ⇒ SMCJ170-E3/57T      |
| ↔ SN74AUC1G02YZPR     | ⊛ SP1490EEP            | ⊣ TLE4275D      | ⊛ VUI72-14N01     | ⇒ XC6209B152DR        |