

	<h2 style="color: #D9534F;">ZL40209LDF1</h2>	
	Manufacturer Part Number:	ZL40209LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFF MUX 2:6 750MHZ 32QFN
	Datasheets:	1.ZL40209LDF1.pdf 2.ZL40209LDF1.pdf 3.ZL40209LDF1.pdf
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	









Specifications

Part Number	ZL40209LDF1
Manufacturer	Microsemi
Description	IC CLK BUFF MUX 2:6 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	2:6
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40209LDF1 is New Original in Stock, Search ZL40209LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40209LDF1 Microsemi with warrantied and confidence. RFQ
 ZL40209LDF1 : Info@Y-IC.com

You May Be Also Be interested

In:

 ZL40208LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN	 ZL40209LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN	 ZL40210LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40211LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN
 ZL40208LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN	 ZL40207LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN	 ZL40207LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN	 ZL40206LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN

Hot Parts More

- | | | | | |
|-------------------|--------------------|-------------------|--------------------|--------------------|
| 06035A271G4T2A | 12101U151KAT2A | 2220GC222KAT1A | A8654KLPTR | AH180-SNG-7 |
| AT24MAC602-STUM-T | AUR9712AGQR | BAW101-7 | BZX384C3V6-E3-08 | CMS30I30A |
| CPDQR12V0U-HF | D210U1000B | E7.5W24R5 | EP4CE10F17I7N | FQPF3P20 |
| FXL4TD245UMX | GAL20RA10-12LP | GCDA15C-1-GS08 | GRM0335C2A9R5CA01D | GRM155R61A105ME15D |
| IPB60R199CP | IRFBC40STRR | IRFR3704Z | LM3503SQ-16/NOPB | LQG15HS4N3S02D |
| LT1949EMS8#TRPBF | LTC260ICDD | LTC3350EUHF#TRPBF | LTL42TB6N | LTST-C193TGKT |
| MAX8855ETJ+T | NJM2882F15 | PS21962-4T | RA07M4047M | RKZ10DKU |
| RT9701CBL | SC18IS600IBS | SI7540ADP-T1-GE3 | SKM300GB066D | SLG55221-130010VTR |
| SMCJ22A-TR | SN74LVC1GU04DCKRG4 | SN75LBC968 | SPU0414HR5H-PB | ST72651AR6T1/NYM |
| TA8880CN | TISP4070L3AJR-S | TLV3012AIDBVRG4 | VI-263-EM/F2 | VTQ30-04D013 |