


 A Renesas Company	ISL1539IVEZ-T7
	Manufacturer Part Number: ISL1539IVEZ-T7
	Manufacturer/Brand: Intersil
	Part of Description: IC VDSL2 LINE DVR AMP 24HTTSOP
Datasheets:  ISL1539IVEZ-T7.pdf	RoHS Status:  Lead free / RoHS
Stock Condition: Compliant New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL1539IVEZ-T7
Manufacturer	Intersil
Description	IC VDSL2 LINE DVR AMP 24HTTSOP
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Driver
Package / Case	24-TSSOP (0.173", 4.40mm Width) Exposed Pad
Supplier Device Package	24-HTSSOP
Voltage - Supply	±5 V ~ 15 V
Protocol	VDSL2
Number of Drivers/Receivers	4/0
Duplex	-
Data Rate	-
Packaging	Tape & Reel (TR)

ISL1539IVEZ-T7 is New Original in Stock, Search ISL1539IVEZ-T7 Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL1539IVEZ-T7 Intersil with warrantied and confidence. RFQ ISL1539IVEZ-T7 : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL1539IVEZ Intersil IC VDSL2 LINE DVR AMP 24HTTSOP	 ISL1540IRZ-T13 Intersil IC DRVIER ADSL DUAL 32QFN	 ISL1540IRZ-T7 Intersil IC DRVIER ADSL DUAL 32QFN	 ISL1539IRZ-T7 Intersil IC VDSL2 LINE DVR AMP 24QFN
 ISL1539IRZ-TZ INTERSI ISL1539IRZ-TZ INTERSI	 ISL1540IRZ Intersil ISL1540IRZ INTERSIL	 ISL1549IRZ INTERSI INTERSI QFN	 ISL1539IRZ-T13 Intersil IC VDSL2 LINE DVR AMP 24QFN

Hot Parts

More

- | | | | | |
|----------------------|------------------|-------------------|------------------------|----------------------|
| ⊛ 12061A331KAT4A | ↔ 2220SC393KAZ1A | ⇒ 7MBP50JR060 | D AD50F08KEC | ⇒ AM80A-048L-018F60L |
| ⊣ APL5301-18AC-TRL | ⊛ AR7645-LF | D AT25256B-XHL-T | ⇒ ATS177-PG-A-B | ⇒ AZ4558AMTR |
| ⊛ BM22-3H103FB-100-F | ⊣ BTN3904N3 | ⊛ CDCEL937QPWRQ1 | ↔ CGA2B2NP01H121J050BA | ⇒ CS401-21IO2 |
| D CY22381SXC-157T | ⊛ DAC80-CBI-I | ⊣ DMC4050SSDQ | ⊛ ECH8310-TL-H | ⇒ ESDA6V1W5-5TR |
| ⇒ GRM1557U1H4R0CZ01D | ↔ LQP03TN7N5H02D | ⊛ LT3080IMS8E#PBF | ⊣ LTC3208EUH#PBF | ⇒ M57962L01R |
| ↔ MB86435PF | ⇒ MC34184DR2G | D MCC310-16I01B | ⊛ MG100G2CL1 | ⊣ ML6428CS2X |
| ⊛ MURS160-13-F | D NJM2732E | ⇒ NUP1105LT1G | ↔ PIC10F202T-I/MC071 | ⇒ PTVS54VS1UR |
| ⊣ RD65FY04 | ⊛ S560-6600-Z6 | ↔ SI3983DV-T1-GE3 | ⇒ SKM200GAR12E4 | ⇒ SMAJ220A-TP |
| ⊛ SP3050-04HTG | ⊣ SPX3819R2-L/TR | ⊛ SSL2129AT/1J | D STD5N62K3 | ⇒ SZMMBZ5270BLT1G |
| ↔ T659N26TOF | ⊛ TB1306AFG | ⊣ TLC2932PWR | ⊛ TPS2231PWG4 | ⇒ ZXMM10A08E6T |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited