	<p>LB1939</p>
	<p>Manufacturer Part Number: LB1939</p> <p>Manufacturer/Brand: SANYO</p> <p>Part of Description: SANYO SMD</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 2900 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	LB1939
Manufacturer	SANYO
Description	SANYO SMD
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2900 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

LB1939 is New Original in Stock, Search LB1939 Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1939 with warrantied and confidence. RFQ LB1939 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>LB1938FA-BH AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 8MICRO</p>	 <p>LB1940T-MPB-E AMI Semiconductor / ON Semiconductor IC BRIDGE DRIVER PAR TSSOP-20</p>	 <p>LB1939T-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 20TSSOP</p>	 <p>LB1938FAGEVB AMI Semiconductor / ON Semiconductor EVAL BOARD H-BRIDGE MOTOR DVR</p>
 <p>LB1939TGEVB AMI Semiconductor / ON Semiconductor EVAL BOARD FOR LB1939T</p>	 <p>LB1938T-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 8MSOP</p>	 <p>LB1939T SANYO SANYO TSSOP</p>	 <p>LB1938T-TLM SANYO LB1938T-TLM SANYO</p>

Hot Parts

More

- | | | | | |
|---------------------|--------------------|-----------------------|----------------------|----------------------|
| ⊕ 06035A271GAT4A | ➔ 08052U0R8BAT2A | ➔ 12061A430FAT2A | D 1SMA5924BT3 | ➔ ADM1815-20ART-REEL |
| ⊖ ATMEGA16M1-15AD | ⊕ BKO-C2144H02 | D C1608COG1H331JT000N | ➔ C5750CH2A154J230KA | ➔ CC1206JKNPOCBN271 |
| ⊕ CM3312R111R-15 | ⊖ CM88L70CSI | ⊕ CS550-12io1 | ➔ D121N600B | ➔ D153-1000-50 |
| D DF2S5.6S | ⊕ DS1640SN+TR | ⊖ DT28F160S570 | ⊕ DV827C-1100-28 | ➔ EL5629BEZ |
| ➔ ERJ-1TRQFR22U | ➔ F6QA2G140M2AM | ⊕ GRM0225C1E3R3CA03L | ⊖ GRM216R71E103KA01D | ➔ IRLR3303TRPBF |
| ➔ LD055C103JAB2A | ➔ LM5122MHX/NOPB | D LT3481IMSE#PBF | ⊕ LT6000IDCB#TRPBF | ⊖ MAX2992ECB+T |
| ⊕ MAX778CSA | D MBRAF440T3G | ➔ MC145557L | ➔ MMSZ5236AS | ➔ NP3100SB1G |
| ⊖ P2H60QH20 | ⊕ PBSS306NX | ➔ PT6643M-12V | ➔ RSX101VA | ➔ SM1125ADV |
| ⊕ SN74LVTH32245ZKER | ⊖ SQCB7M0R6BA8TAQ | ⊕ STTH2003CG | D T1078F04TSL | ➔ TPS780330220DBVR |
| ➔ TR/3216FF6.5-R | ⊕ TR3C336K020C0350 | ⊖ UC2637DWTR | ⊕ WPD95-20 | ➔ YBG1105W-11-TR |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited