


	<h2 style="color: red;">SP809EK-L-2-9/TR</h2>	
	Manufacturer Part Number:	SP809EK-L-2-9/TR
	Manufacturer/Brand:	Exar Corporation
	Part of Description:	IC MPU RESET CIRC 2.9V SOT23-3
Datasheets:	 SP809EK-L-2-9/TR.pdf	
RoHs Status:	 Lead free / RoHS Compliant	
Stock Condition:	New original, 27276 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	SP809EK-L-2-9/TR
Manufacturer	Exar Corporation
Description	IC MPU RESET CIRC 2.9V SOT23-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	27276 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	TO-236-3, SC-59, SOT-23-3
Supplier Device Package	SOT-23-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.9V
Packaging	Tape & Reel (TR)













































SP809EK-L-2-9/TR is New Original in Stock, Search SP809EK-L-2-9/TR Datasheets, PDF, Inventory at Y-IC.com Online, Order SP809EK-L-2-9/TR Exar Corporation with warrantied and confidence. RFQ SP809EK-L-2-9/TR : Info@Y-IC.com

You May Be Also Be interested In:

 <p>SP809EK-L-2-3/TR Exar Corporation IC MPU RESET CIRC 2.3V SOT23-3</p>	 <p>SP809EK-L-3-1 Exar SP809EK-L-3-1 Exar</p>	 <p>SP809EK-L-2-6 Exar SP809EK-L-2-6 Exar</p>	 <p>SP809EK-L-2-6/TR Exar Corporation IC MPU RESET CIRC 2.6V SOT23-3</p>
 <p>SP809EK-L-2.6/TR SIPEX SP809EK-L-2.6/TR SIPEX</p>	 <p>SP809EK-L-2.9/TR EXAR SP809EK-L-2.9/TR EXAR</p>	 <p>SP809EK-4.6/TR SIPEX SP809EK-4.6/TR SIPEX</p>	 <p>SP809EK-L-2.6 SIPEX SIPEX SOT-23</p>

Hot Parts

[More](#)

 SP8009EL	 SP800LCN	 SP800MCN	D SP800MCN-L	 SP8034CB-2
 SP805-2R0	 SP809EK-2-3/TR	D SP809EK-2-6/TR	 SP809EK-2-9/TR	 SP809EK-2.6/TR
 SP809EK-2.9/TR	 SP809EK-3-1/TR	 SP809EK-3.1/TR	 SP809EK-4-0/TR	 SP809EK-4-4/TR
D SP809EK-4-6/TR	 SP809EK-4.0/TR	 SP809EK-4.4/TR	 SP809EK-4.6/TR	 SP809EK-L-2-3/TR
 SP809EK-L-2-6	 SP809EK-L-2-6/TR	 SP809EK-L-2-9	 SP809EK-L-2.3/TR	 SP809EK-L-2.6/TR
 SP809EK-L-2.9/TR	 SP809EK-L-3-1	D SP809EK-L-3-1/TR	 SP809EK-L-3.1/TR	 SP809EK-L-4-0
 SP809EK-L-4-0/TR	D SP809EK-L-4-4	 SP809EK-L-4-6/TR	 SP809EK-L-4.0/TR	 SP809EK-L-4.4/TR
 SP809EK-L-4.6/TR	 SP809NEK-2-6/TR	 SP809NEK-2-9/TR	 SP809NEK-2.3/TR	 SP809NEK-2.9
 SP809NEK-2.9/TR	 SP809NEK-3.1/TR	 SP809NEK-4-6/TR	D SP809NEK-4.4	 SP809NEK-4.6/TR
 SP809NEK-L-2-3/TR	 SP809NEK-L-2-6-TR	 SP809NEK-L-2-9/TR	 SP809NEK-L-2.3/TR	 SP809NEK-L-3-1/TR

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited