

	<b>MAX5942BCSE</b>	
	<b>Manufacturer Part Number:</b>	MAX5942BCSE
<b>Manufacturer/Brand:</b>	MAXIM	
<b>Part of Description:</b>	MAX5942BCSE MAXIM	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 174 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		









### Specifications

Part Number	MAX5942BCSE
Manufacturer	MAXIM
Description	MAX5942BCSE MAXIM
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	174 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MAX5942BCSE is New Original in Stock, Search MAX5942BCSE Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX5942BCSE with warrantied and confidence. RFQ MAX5942BCSE : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>MAX5942BESE+T</b> Maxim Integrated IC IEEE 802.3AF POE SYSTM 16SOIC</p>	 <p><b>MAX5942BCSE+T</b> Maxim Integrated IC IEEE 802.3AF POE SYSTM 16SOIC</p>	 <p><b>MAX5942ACSE+</b> Maxim Integrated IC IEEE 802.3AF POE SYSTM 16SOIC</p>	 <p><b>MAX5942ACSE+T</b> Maxim Integrated IC IEEE 802.3AF POE SYSTM 16SOIC</p>
 <p><b>MAX5943AESE</b> MAXIM MAX5943AESE MAXIM</p>	 <p><b>MAX5942BESE</b> MAXIM MAXIM SOP16</p>	 <p><b>MAX5942AESE</b> MAXIM MAXIM SOP16</p>	 <p><b>MAX5942AESE+</b> Maxim Integrated IC IEEE 802.3AF POE SYSTM 16SOIC</p>

### Hot Parts

More

- |                      |                        |                      |                      |                      |
|----------------------|------------------------|----------------------|----------------------|----------------------|
| ⚙ 6MBI50J-060        | ➡ ADSP-BF542BBCZ-5A    | ➡ AH173WL-7-A        | D APT2X30D60J        | ➡ BU4030BF           |
| ⚡ C3216JB2A224K115AA | ⚙ CC0402KRX7R9BB682    | D CMLDM8120GTR-LF    | ➡ DT36N600KOC        | ➡ ELM34600AA-N       |
| ⚙ FC3300-LF-AC       | ⚡ FDD6635-NL           | ⚙ GJM0335C1E1R7WB01D | ➡ GRM1555C1H680JA01J | ➡ GRM188R71C474KA88D |
| D IR35207MTRPBF      | ⚙ L1117L-2.85          | ⚡ LDB211G7320C-001   | ⚙ LMP7702MAX/NOPB    | ➡ LQP03TN6N8J04D     |
| ➡ MA2SD1000L         | ➡ MC33170DTBR2         | ⚙ MC33274AD/D        | ⚡ MC74LVX244DTG      | ➡ MK3734SLFTR        |
| ➡ MMG400D170B6EN     | ➡ MSM5414260E-60TSK-R1 | D N3930ZC160         | ⚙ R1RW0408DGE-2PI    | ⚡ R5F64122PFE        |
| ⚙ S-817A32ANB-CUV-T2 | D SAFEB1G96AL0F00R15   | ➡ SI4936ADY-T1       | ➡ SKIIP39AC126V1     | ➡ SKKL500/14E        |
| ⚡ SM2G200US60        | ⚙ SN74GTL2006PWRG4     | ➡ SPH252012H1R0MTY04 | ➡ ST733C08LHK2L      | ➡ STB10NB50-1        |
| ⚙ STP90N4F3          | ⚡ TC1223-3.0VCT713     | ⚙ TC164-JR-073K3     | D TMP105YZCR         | ➡ TPSB105M035R0100   |
| ➡ UF1050A-IC-E       | ⚙ UPC2722GR-E1         | ⚡ WM8950GEFL/RV      | ⚙ X9315WMIT1         | ➡ XC3S1000-4FG456C   |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited